

| Ref. No. | Date      | Time  | Location  | Construction Noise Level | Unit        | Action Level   | Limit Level | Follow-up action                                    |  |
|----------|-----------|-------|---|--------------------------|-------------|--|-------------|---|--|
| X_10N158 | 5-Mar-14  | 15:26 | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 71                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                    | Traffic nearby was observed during monitoring and was considered as the major noise contribution.  |
|          |           |       |   |                          |             |  |             | Action taken / to be taken:<br>Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Welding and grouting works at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.             |
| X_10N159 | 11-Mar-14 | 13:30 | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 72                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                    | Traffic nearby was observed during monitoring and was considered as the major noise contribution.  |
|          |           |       |   |                          |             |  |             | Action taken / to be taken:<br>Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Rebar fixing and concrete curing works at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby. |



| Ref. No. | Date      | Time  | Location  | Construction Noise Level | Unit        | Action Level   | Limit Level | Follow-up action                                    |  |
|----------|-----------|-------|---|--------------------------|-------------|--|-------------|---|--|
| X_10N160 | 2-Apr-14  | 10:30 | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 73                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                    | Traffic nearby was observed during monitoring and was considered as the major noise contribution.  |
|          |           |       |   |                          |             |  |             | Remarks / Other Obs:                                | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Welding removal and bracket installtionworks at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.                             |
| X_10N161 | 8-Apr-14  | 9:50  | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 74                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 65          | Possible reason:                                    | Traffic nearby was observed during monitoring and was considered as the major noise contribution.  |
|          |           |       |   |                          |             |  |             | Action taken / to be taken:<br>Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Bracket installtion works and dolphin works installation at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.                 |
| X_10N162 | 15-Apr-14 | 9:10  | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 72                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                    | Traffic nearby was observed during monitoring and was considered as the major noise contribution.  |
|          |           |       |   |                          |             |  |             | Action taken / to be taken:<br>Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Bracket installtion works sealing works for dolphin cap; concreting works for crosshead for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby. |



| Ref. No. | Date      | Time  | Location  | Construction Noise Level | Unit        | Action Level   | Limit Level | Follow-up action                                 |   |
|----------|-----------|-------|---|--------------------------|-------------|--|-------------|--|---|
| X_10N163 | 7-May-14  | 15:11 | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 73                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                 | Traffic nearby was observed during monitoring and was considered as the major noise contribution.   |
|          |           |       |   |                          |             |  |             | Remarks / Other Obs:                             | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Sealing and weilding works for dolphin cap under Contract Hy200919 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby. |
| X_10N164 | 14-May-14 | 16:30 | M6 - HK Baptist<br>Church Henrietta<br>Secondary School | 71                       | Leq(30-min) | when one<br>documented<br>complaint was<br>received. | 70          | Possible reason:                                 | Traffic nearby was observed during monitoring and was considered as the major noise contribution.   |
|          |           |       |   |                          |             |  |             | Action taken / to be taken: Remarks / Other Obs: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Welding works for dolphin cap under Contract Hy200919 was conducted around the concerned location during the time of measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.       |