



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action
X_10N145	5-Nov-13	14:30	M6 - HK Baptist Church Henrietta Secondary School	74	Leq(30-min)	when one documented complaint was received.	70	<p>Possible reason: Traffic nearby was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.</p> <p>Remarks / Other Obs: Formwork and falsework removal for Contract HY/2009/19 were conducted during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.</p>



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action
X_10N147	18-Nov-13	13:35	M6 - HK Baptist Church Henrietta Secondary School	72	Leq(30-min)	when one documented complaint was received.	70	<p>Possible reason: Traffic nearby was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.</p> <p>Remarks / Other Obs: Formwork and Rebar fixing for Contract HY/2009/19 were conducted during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.</p>



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action
X_10N148	26-Nov-13	10:45	M6 - HK Baptist Church Henrietta Secondary School	72	Leq(30-min)	when one documented complaint was received.	70	<p>Possible reason: Traffic nearby was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.</p> <p>Remarks / Other Obs: Formwork, falsework installation and cofferdam installation for Contract HY/2009/19 were conducted during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.</p>



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10C597	1-Nov-13	Mid-flood	P3	DO(mg/L)	3.34	3.36	2.73	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	3.00	9.10	10.25	Action taken / to be taken: Immediate repeated measurement was conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	6.00	15.00	22.13	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_10C598	11-Nov-13	Mid-flood	P5	DO(mg/L)	5.09	3.36	2.73	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	10.51	9.10	10.25	Action taken / to be taken: Immediate repeated measurement was conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	12.00	15.00	22.13	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_10C599	15-Nov-13	Mid-flood	C1	DO(mg/L)	4.63	3.36	2.73	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	7.97	9.10	10.25	Action taken / to be taken: Immediate repeated measurement was conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	22.50	15.00	22.13	Remarks / Other Obs: In view of no marine work was conducting in the vicinity of the monitoring location on that day and the view that no further exceedance was recorded in the next consecutive monitoring and the silt screen was in proper condition, the exceedance was considered not project related.
X_10C600	19-Nov-13	Mid-ebb	P1	DO(mg/L)	4.63	3.36	2.73	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	9.22	9.10	10.25	Action taken / to be taken: Immediate repeated measurement was conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	6.00	15.00	22.13	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_10C601	25-Nov-13	Mid-flood	C7	DO(mg/L)	3.35	3.36	2.73	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	1.45	9.10	10.25	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	4.50	15.00	22.13	Remarks / Other Obs: Silt screen was in proper condition. In view of no marine works was conducted in the vicinity of the monitoring location on monitoring day and no further exceedance was recorded in the next consecutive monitoring, the exceedance was considered not project related.



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D345	28-Oct-13	Mid-Flood	C7	Middle	DO(mg/l)	3.26	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D346	28-Oct-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.10	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D347	28-Oct-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	3.59	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D348	28-Oct-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	3.64	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D349	30-Oct-13	Mid-Flood	C7	Middle	DO(mg/l)	3.33	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D350	30-Oct-13	Mid-Flood	Ex-WPCWA SW	Middle	DO(mg/l)	3.44	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D351	30-Oct-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.30	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D352	30-Oct-13	Mid-Ebb	C7	Middle	DO(mg/l)	3.71	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D353	30-Oct-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	3.32	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D354	1-Nov-13	Mid-Ebb	C7	Middle	DO(mg/l)	3.16	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D355	4-Nov-13	Mid-Flood	Ex-WPCWA SW	Middle	DO(mg/l)	3.44	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D356	4-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.30	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D357	4-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	4.13	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D358	6-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	3.28	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D359	8-Nov-13	Mid-Flood	C6	Bottom	DO(mg/l)	3.70	4.14	3.33	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities at C6, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D360	8-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	3.10	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D361	8-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	3.27	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D362	11-Nov-13	Mid-Flood	C7	Middle	DO(mg/l)	3.33	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D363	11-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.84	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D364	11-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	3.60	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D365	11-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	3.25	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D366	13-Nov-13	Mid-Flood	C7	Middle	DO(mg/l)	3.36	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D367	13-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.82	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D368	15-Nov-13	Mid-Flood	C7	Middle	DO(mg/l)	3.81	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D369	15-Nov-13	Mid-Ebb	C7	Middle	DO(mg/l)	3.26	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D370	19-Nov-13	Mid-Flood	C7	Middle	DO(mg/l)	3.35	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>
X_10D371	19-Nov-13	Mid-Flood	Ex-WPCWA SW	Middle	DO(mg/l)	3.50	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D372	19-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	3.46	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: In view that there was no marine activities at ex-WPCWA and organic pollutant was observed discharged from nearby culvert, it was considered not related to Project works.</p>
X_10D373	19-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	0.95	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D374	19-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	1.42	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D375	21-Nov-13	Mid-Flood	Ex-WPCWA SW	Middle	DO(mg/l)	2.92	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: Owing to minimal flushing combined with organic dischargeduring ebb tide. DO level was observed improved during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D376	21-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	2.80	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: Owing to minimal flushing combined with organic dischargeduring ebb tide. DO level was observed improved during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D377	21-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	1.32	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D378	21-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	1.21	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D379	23-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	1.42	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D380	23-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	1.47	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D381	25-Nov-13	Mid-Flood	C7	Middle	DO(mg/l)	3.51	3.87	3.09	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Immediate repeated measurements had conducted to confirm the exceedances. No odour nuisance was detected during the DO monitoring. Checked with Contractor works. Checking with the Contractor's daily records.</p> <p>Remarks / Other Obs: Silt screen was in proper condition in their daily inspection. In view that there was no marine activities and, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_10D382	25-Nov-13	Mid-Flood	Ex-WPCWA SE	Middle	DO(mg/l)	4.03	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: Owing to minimal flushing combined with organic dischargeduring ebb tide. DO level was observed improved during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D383	26-Nov-13	Mid-Ebb	Ex-WPCWA SW	Middle	DO(mg/l)	1.47	3.84	3.73	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>
X_10D384	26-Nov-13	Mid-Ebb	Ex-WPCWA SE	Middle	DO(mg/l)	1.59	4.26	3.61	<p>Possible reason: Possible in relation to the accumulation of organic particles discharged from culvert near monitoring station</p> <p>Action taken / to be taken: Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checked with Contract works.</p> <p>Remarks / Other Obs: It was observed that natural tidal flushing was minimal during ebb tide. DO level was observed replenished during flood tide cycle. The DO level at the concerned location will be keep in view closely and additional measures should be considered when necessary. DO level was observed restored during both ebb and flood tide since 28 November 2013 In view that there was no marine activities at ex-WPCWA, it was considered not related to Project works.</p>



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W499	28-Oct-13	Mid-Flood	WSD21	DO(mg/L)	3.64	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	5.75	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	4.50	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.
X_W500	28-Oct-13	Mid-Flood	WSD19	DO(mg/L)	4.11	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	13.75	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	4.50	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. The exceedances was considered not project related.
X_W501	28-Oct-13	Mid-Ebb	WSD21	DO(mg/L)	3.36	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	7.91	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	8.00	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.
X_W502	30-Oct-13	Mid-Flood	WSD9	DO (mg/L)	6.80	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.73	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				Suspended Solid	10.00	13.00	14.43	Remarks / Other Obs: In view of no marine work was conducted on that day and WSD9 was located at the upstream of the Project, the exceedances was considered not project related.
X_W503	30-Oct-13	Mid-Flood	WSD17	DO(mg/L)	4.46	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	11.58	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	11.50	13.00	14.43	Remarks / Other Obs: In view of No marine work was conducting during water quality monitoring, the exceedances was considered not project related.
X_W504	30-Oct-13	Mid-Flood	WSD19	DO(mg/L)	5.69	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	9.90	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	8.50	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. The exceedances was considered not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W505	30-Oct-13	Mid-Ebb	WSD9	DO (mg/L)	5.25	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	11.03	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				Suspended Solid	4.50	13.00	14.43	Remarks / Other Obs: In view of no marine works was conducted on that day and no further exceedance was recorded in the next consecutive monitoring and since WSD9 was located at the downstream of the Project, in view that the water quality at monitoring stations located nearest the marine work site were well below the Action level, the exceedances was considered not project related.
X_W506	30-Oct-13	Mid-Ebb	WSD17	DO(mg/L)	3.48	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.74	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	5.00	13.00	14.43	Remarks / Other Obs: In view of no marine work was conducting on that day, the exceedances was considered not project related.
X_W507	30-Oct-13	Mid-Ebb	WSD21	DO(mg/L)	3.99	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.84	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	5.50	13.00	14.43	Remarks / Other Obs: In view of no marine work was conducting during water quality monitoring. Silt screen was confirmed in order, the exceedances was considered not project related.
X_W508	30-Oct-13	Mid-Ebb	WSD19	DO(mg/L)	3.43	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	11.12	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	11.50	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_W509	1-Nov-13	Mid-Flood	WSD17	DO(mg/L)	5.60	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	13.01	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	14.00	13.00	14.43	Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the monitoring location was located upstream the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related
X_W510	1-Nov-13	Mid-Flood	WSD21	DO(mg/L)	3.37	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	2.73	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	3.00	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W511	1-Nov-13	Mid-Flood	WSD19	DO(mg/L)	4.00	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	9.74	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	9.00	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. The exceedances was considered not project related.
X_W512	1-Nov-13	Mid-Ebb	WSD19	DO(mg/L)	4.11	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	11.25	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	10.00	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_W513	4-Nov-13	Mid-Flood	WSD17	DO(mg/L)	5.91	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.80	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	7.50	13.00	14.43	Remarks / Other Obs: No marine work was conducting during water quality monitoring. The water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
X_W514	4-Nov-13	Mid-Flood	WSD19	DO(mg/L)	5.52	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	9.48	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	6.00	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. The exceedances was considered not project related.
X_W515	4-Nov-13	Mid-Ebb	WSD9	DO (mg/L)	6.39	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.93	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. The tidal was moving westward.
				Suspended Solid	19.00	13.00	14.43	Remarks / Other Obs: In view of no marine works was conducted on that day and no further exceedance was recorded in the next consecutive monitoring and since WSD9 was located at the upstream of the Project, in view that the water quality at monitoring stations located nearest the marine work site were well below the Action level, the exceedances was considered not project related.
X_W516	4-Nov-13	Mid-Ebb	WSD17	DO(mg/L)	6.67	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	11.03	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	10.50	13.00	14.43	Remarks / Other Obs: In view of no marine work was conducting on that day and the water quality at monitoring stations located nearest the marine work site were well below the Action level, the exceedances was considered not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W518	4-Nov-13	Mid-Ebb	WSD19	DO(mg/L)	6.66	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	15.57	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. .
				SS	8.00	13.00	14.43	Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation measures including framed silt curtain was confirmed in place. In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
X_W519	6-Nov-13	Mid-Flood	WSD21	DO(mg/L)	4.48	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	8.68	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	13.50	13.00	14.43	Remarks / Other Obs: In view of no marine work was conducting during water quality monitoring. Silt screen was confirmed in order, the exceedances was considered not project related.
X_W520	8-Nov-13	Mid-Flood	WSD17	DO(mg/L)	4.23	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station.
				Turbidity	14.53	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works.
				SS	6.50	13.00	14.43	Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the monitoring location was located upstream the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related
X_W521	8-Nov-13	Mid-Flood	WSD21	DO(mg/L)	3.53	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	4.28	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	11.50	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.
X_W522	8-Nov-13	Mid-Ebb	WSD21	DO(mg/L)	3.65	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	2.28	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	6.00	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.
X_W523	11-Nov-13	Mid-Ebb	WSD21	DO(mg/L)	3.24	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.
				Turbidity	3.32	8.04	9.49	Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.
				SS	8.00	13.00	14.43	Remarks / Other Obs: Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W524	13-Nov-13	Mid-Flood	WSD17	DO(mg/L)	4.34	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: In view of no marine work was conducting during water quality monitoring, the exceedances was considered not project related.
				Turbidity	9.43	8.04	9.49	
				SS	10.00	13.00	14.43	
X_W525	13-Nov-13	Mid-Flood	WSD19	DO(mg/L)	4.79	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. . Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation meares including framed silt curtain was confirmed in place.The exceedances was considered not project related.
				Turbidity	9.44	8.04	9.49	
				SS	13.00	13.00	14.43	
X_W526	13-Nov-13	Mid-Ebb	WSD21	DO(mg/L)	4.07	3.66	3.28	Possible reason: Natural variation of water quality in the vicinity of the water quality monitoring station WSD21. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record. Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order. Remarks / Other Obs: In view of no marine activitie was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.
				Turbidity	8.77	8.04	9.49	
				SS	11.50	13.00	14.43	
X_W527	13-Nov-13	Mid-Ebb	WSD19	DO(mg/L)	4.84	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. . Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation meares including framed silt curtain was confirmed in place.In view of the monitoring station was located at the upstream of the construction site, the exceedances was considered not project related.
				Turbidity	9.45	8.04	9.49	
				SS	18.50	13.00	14.43	
X_W528	15-Nov-13	Mid-Flood	WSD17	DO(mg/L)	4.57	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: In view of no marine work was conducting during water quality monitoring, the exceedances was considered not project related.
				Turbidity	8.78	8.04	9.49	
				SS	10.00	13.00	14.43	
X_W529	15-Nov-13	Mid-Flood	WSD21	DO(mg/L)	4.72	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record. Inview of no marine work was conducting during water quality monitoring. Silt screen was confirmed in order, the exceedances was considered not project related.
				Turbidity	8.17	8.04	9.49	
				SS	6.00	13.00	14.43	
X_W530	15-Nov-13	Mid-Flood	WSD19	DO(mg/L)	6.61	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. . Remarks / Other Obs: Dredging works was conducted by Contractor HK/2012/08 during monitoring. Mitigation meares including framed silt curtain was confirmed in place.The exceedances was considered not project related.
				Turbidity	10.53	8.04	9.49	
				SS	10.00	13.00	14.43	



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W531	15-Nov-13	Mid-Ebb	WSD17	DO(mg/L)	4.14	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
				Turbidity	9.24	8.04	9.49	
				SS	7.00	13.00	14.43	
X_W532	15-Nov-13	Mid-Ebb	WSD21	DO(mg/L)	4.12	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record. Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
				Turbidity	9.61	8.04	9.49	
				SS	19.00	13.00	14.43	
X_W533	19-Nov-13	Mid-Flood	WSD17	DO(mg/L)	7.06	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the monitoring location was located upstream the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
				Turbidity	8.72	8.04	9.49	
				SS	10.50	13.00	14.43	
X_W534	21-Nov-13	Mid-Flood	WSD17	DO(mg/L)	4.05	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: According to contractor record, silt screen washing was conducted on that day. In view of no marine work was conducting on that day and the monitoring location was located upstream the water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
				Turbidity	11.09	8.04	9.49	
				SS	10.50	13.00	14.43	
X_W535	23-Nov-13	Mid-Flood	WSD17	DO(mg/L)	4.98	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Remarks / Other Obs: No marine work was conducting during water quality monitoring. The water quality at monitoring stations located downstream marine work site were well below the Action level, the exceedances was considered not project related.
				Turbidity	8.40	8.04	9.49	
				SS	10.00	13.00	14.43	
X_W536	23-Nov-13	Mid-Flood	WSD21	DO(mg/L)	4.62	3.66	3.28	Possible reason: Natural variation or changes of water quality in the vicinity of the water quality monitoring station. Action taken / to be taken: Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record. Remarks / Other Obs: In view of no marine work was conducting during water quality monitoring. Silt screen was confirmed in order, the exceedances was considered not project related.
				Turbidity	7.97	8.04	9.49	
				SS	13.50	13.00	14.43	



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_W537	23-Nov-13	Mid-Ebb	WSD21	DO(mg/L)	3.40	3.66	3.28	Possible reason:
				Turbidity	1.90	8.04	9.49	Action taken / to be taken:
				SS	<2	13.00	14.43	Remarks / Other Obs:
<p>Natural variation of water quality in the vicinity of the water quality monitoring station WSD21.</p> <p>Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.</p> <p>Additional water diffuser system installed at monitoring station WSD21 was observed operating during monitoring. Silt screen was confirmed in order.</p> <p>In view of no marine activities was conducted during monitoring and no further exceedance was recorded in the next consecutive monitoring, the exceedances was considered not project related.</p>								
X_W538	25-Nov-13	Mid-Flood	WSD21	DO(mg/L)	4.11	3.66	3.28	Possible reason:
				Turbidity	10.36	8.04	9.49	Action taken / to be taken:
				SS	5.50	13.00	14.43	Remarks / Other Obs:
<p>Natural variation or changes of water quality in the vicinity of the water quality monitoring station.</p> <p>Immediate repeated in-situ measurements had conducted to confirm the exceedances. Checking with contractor's works. Checking with contractor's inspection record.</p> <p>In view of no marine work was conducting during water quality monitoring. Silt screen was confirmed in order, the exceedances was considered not project related.</p>								