



Ref no.	Date	Tide	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_16CR024	9 Dec 2016	Mid-flood	M5B	DO(mg/L)	6.12	4.60	3.00	Possible reason:	Changes of water quality in the vicinity of water quality monitoring station possibly in relate to nearby culvert discharge.
				SS(mg/L)	14.00	12.00	17.00	Action taken/ to be taken:	Checking with the contractor works and review previous monitoring data.
				Remarks/ Other Obs:	Trimming of rock mound profile was conducted under Contract HK/2012/08 on the monitoring date. Contractor mitigation measures including the use of silt curtain was in place while no particular observation regarding water quality impact was observed during sampling. In view of the above, it was considered that the exceedance was not related to Project. No exceedance was recorded on the subsequent monitoring on 12 December 2016 ebb tide.				
X_16CR025	12 Dec 2016	Mid-flood	M5B	DO(mg/L)	6.66	4.60	3.00	Possible reason:	Changes of water quality in the vicinity of water quality monitoring station possibly in relate to nearby culvert discharge.
				SS(mg/L)	18.00	12.00	17.00	Action taken/ to be taken:	Checking with the contractor works and review previous monitoring data.
				Remarks/ Other Obs:	Trimming of rock mound profile was conducted under Contract HK/2012/08 on the monitoring date. Contractor mitigation measures including the use of silt curtain was in place while no particular observation regarding water quality impact was observed during sampling. In view of the above, it was considered that the exceedance was not related to Project. No exceedance was recorded on the subsequent monitoring on 14 December 2016 ebb tide.				