



| Ref no. | Date | Tide | Location | Parameter (Unit) | Measured | Action Level | Limit Level | Follow-up action | |
|-----------|-----------|---------|----------|----------------------|---|--------------|-------------|----------------------------|---|
| X_16CR032 | 9-Aug-17 | Mid-ebb | M5B | DO (mg/L) | 4.28 | 4.60 | 3.00 | Possible reason: | Changes of water quality in the vicinity of water quality monitoring station possibly in relate to nearby culvert discharge. |
| | | | | SS (mg/L) | 2.50 | 12.00 | 17.00 | Action taken/ to be taken: | Immediate repeated in-site measurement had conducted to confirm the exceedance. Checking with the contractor works and review previous monitoring data. |
| | | | | Remarks/ Other Obs.: | No marine construction activity was conducted under Contract HK/2012/08 on the monitoring date while nearby culvert discharge was observed. In view of no marine construction activity conducted, it was considered that the exceedance was not related to Project. No exceedance was recorded on the subsequent monitoring on 9 August 2017 flood tide. | | | | |
| X_16CR033 | 21-Aug-17 | Mid-ebb | M5B | DO (mg/L) | 4.64 | 4.60 | 3.00 | Possible reason: | Changes of water quality in the vicinity of water quality monitoring station possibly in relate to nearby culvert discharge. |
| | | | | SS (mg/L) | 13.50 | 12.00 | 17.00 | Action taken/ to be taken: | Immediate repeated in-site measurement had conducted to confirm the exceedance. Checking with the contractor works and review previous monitoring data. |
| | | | | Remarks/ Other Obs.: | No marine construction activity was conducted under Contract HK/2012/08 on the monitoring date while nearby culvert discharge was observed. In view of no marine construction activity conducted, it was considered that the exceedance was not related to Project. No exceedance was recorded on the subsequent monitoring on 25 August 2017 flood tide. | | | | |