



After checking with contractor HY/2009/19, no construction works were conducted at the concerned location during the recorded period. As such, the exceedances were considered to be contributed by nearby IEC traffic and nearby non- CWB Projects.











After checking with contractor HY/2009/19, no construction works were conducted at the concerned location during the recorded period and the major contribution was considered to be contributed by the adverse weather condition during the hoisting period of Black Rainstorm Warning Signal and not related to Projects

After checking with contractor HY/2009/19, no construction works were conducted at the concerned location during the recorded period and the exceedances were non-continuous and contributed by nearby IEC and slip road traffic.







After checking with contractor HY/2009/19, no major noisy construction works were conducted at the concerned location during the recorded period and the major contribution was considered to be contributed by the adverse weather condition during the hoisting period of Rainstorm Warning Signal and not related to Projects

After checking with contractor HY/2009/19, socket piling works were conducted at the concerned location on the monitoring day. Contractor mitigation measures including erection of temporary noise barrier was in place and piling works at adjacent non-CWB project was observed. In view of the exceedances are non-continuous, the exceedances are considered not related to Projects works