

Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X 10N093	<u>7-Jun-12</u>	<u>13:44</u>	<u>M6 - HK baptist</u> Church henrietta	<u>68</u>	Leq(30-min)	when one documented	<u>65</u>	Possible reason:	No construction activity and traffic nearby was observed during monitoring. Traffic noise contributed as a major noise source during monitoring.
			Secondary School			complaint was	6		Traine heles service and a major heles searce daming merinemigr
						received.			
								Action taken / to be taken:	Reviewed the trend of noise measurement results and analysis of contractor's working procedure. Review the basline noise level at this monitoring station.
								Remarks / Other Obs:	No construction work for Contract no. HY/2009/19 was conducted during the measurement; it is concluded that the exceedance was not due to the Project
									but to traffic noise nearby.
X_10N094	12-Jun-12	<u>16:23</u>	<u>M6 - HK baptist</u> Church henrietta	<u>71</u>	Leq(30-min)	when one documented	<u>65</u>	Possible reason:	No construction activity and traffic nearby was observed during monitoring. Traffic noise contributed as a major noise source during monitoring.
			Secondary School			complaint was	5		<u> </u>
						received.			
								Action taken / to be taken:	Reviewed the trend of noise measurement results and analysis of contractor's working procedure. Review the basline noise level at this monitoring station.
								Remarks / Other Obs:	No construction work for Contract no. HY/2009/19 was conducted during the measurement; it is concluded that the exceedance was not due to the Project
									but to traffic noise nearby.