

13-Feb-14	15:22	M6 - HK Baptist Church Henrietta Secondary School	74		when one		Possible reason:	Traffic nearby was observed during monitoring and was considered as the major noise contribution.
				Leq(30-min)	documented complaint was received.	65		3 · · · · · · · · · · · · · · · · · · ·
					10001104		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Scheduling of concreting hacking off works and use of acoustic mat to minmize potential noise impact to nearby education institute during examination period were implemented by the Contractor
							Remarks / Other Obs:	Welding and support erection works at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.
20-Feb-14	9:39	M6 - HK Baptist Church Henrietta Secondary School	67	Leq(30-min)	when one documented complaint was received.	65	Possible reason:	Traffic nearby was observed during monitoring and was considered as the major noise contribution.
							Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Scheduling of concreting hacking off works and use of acoustic mat to minmize potential noise impact to nearby education institute during examination period were implemented by the Contractor
							Remarks / Other Obs:	Welding works at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.
25-Feb-14	16:05	M6 - HK Baptist Church Henrietta Secondary School	71	Leq(30-min)	when one documented complaint was received.	70	Possible reason:	Traffic nearby was observed during monitoring and was considered as the major noise contribution.
							Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Welding and cleaning works at dolphin cap for Contract HY/2009/19 were conducted around the concerned location during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.
			-Feb-14 9:39 Church Henrietta Secondary School M6 - HK Baptist Church Henrietta	-Feb-14 9:39 Church Henrietta Secondary School 67 M6 - HK Baptist Church Henrietta 71	Feb-14 9:39 Church Henrietta 67 Leq(30-min) -Feb-14 9:39 Church Henrietta 67 Leq(30-min) -Feb-14 16:05 M6 - HK Baptist 71 Leq(30-min)	Feb-14 9:39 Church Henrietta Secondary School Feb-14 16:05 M6 - HK Baptist Church Henrietta Secondary School Feb-14 16:05 M6 - HK Baptist Church Henrietta 71 Leq(30-min) documented complaint was received.	Feb-14 9:39 Church Henrietta Secondary School 67 Leq(30-min) documented complaint was received. 65 M6 - HK Baptist Church Henrietta Secondary School 65 M6 - HK Baptist Church Henrietta 71 Leq(30-min) when one documented complaint was 70 compl	Hereb-14 9:39 M6 - HK Baptist Church Henrietta Secondary School Feb-14 16:05 M6 - HK Baptist Church Henrietta Secondary School Feb-14 16:05 M6 - HK Baptist Church Henrietta Secondary School Feb-14 16:05 M6 - HK Baptist Church Henrietta Secondary School Feb-14 Secondary School Feb-14 National Possible reason: Hereb-14 16:05 M6 - HK Baptist Church Henrietta Secondary School Feb-14 National Possible reason: Hereb-14 16:05 Action taken / to be taken: