

Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N089	2-Apr-12		M6 - HK baptist		Leq(30-min)		65	Possible reason:	No construction activity and traffic nearby was observed during monitoring.
			Church henrietta			documented			Traffic noise contributed as a major noise source during monitoring.
			Secondary School	_,		complaint			
				/1		was received.			
								Action taken / to be taken:	Reviewed the trend of noise measurement results and analysis of contractor's working procedure. Review the basline noise level at this monitoring station.
								Remarks / Other Obs:	No construction work for Contract no. HY/2009/19 was conducted during the measurement; it is concluded that the exceedance was not due to the Project but to traffic noise nearby.