



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_CR005	10-Nov-14	Mid-flood	M5B	DO(mg/l)	7.19	4.60	3.00	Possible reason: Changes of water quality in the vicinity of water quality monitoring station in relate to nearby culvert discharge
				SS	20.00	12.00	17.00	Action taken/ to be taken: Immediate repeated in-situ measurement to confirm the exceedance. Checking with Contractor works and review previous monitoring data. Remarks/ Other Obs: No marine works was conducted under contract HK/2012/08 on the monitoring date, silt curtain installed around intake monitoring station was generally in order. In view of no marine activities conducted on the monitoring date and no further exceedance was recorded in subsequent monitoring, it was considered that the exceedance was not project related.