

Ref no.	Date	Tidal	Location	Parameters	Measured	Action	Limit	Follow-up action	
X_CR015	31-Aug-15	Mid-flood	M5B	DO(mg/l)	4.40	4.60	3.00	Possible reason:	Changes of water quality in the vicinity of water quality monitoring station in relate to nearby culvert discharge
				SS	6.00	12.00	17.00	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedance. Checking with contractor works and review previous monitoring data.
								Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. Mitigation measures including the use of silt curtain was in place and silt curtain installed around intake monitoring station was generally in order while nearby culvert discharge was consistently observed. In view of no marine activity was conducted and no further exceedance was recorded in subsequent monitoring, it was considered that the exceedance was not project related.