



After checking with contractor HY/2009/19, no major noisy construction works were conducted at the concerned location during the recorded period and contractor mitigation measures including erection of temporary noise barrier was confirmed in place. As the exceedance is non-continuous, the exceedances were considered to be contributed by nearby IEC traffic and nearby non- CWB Projects





After checking with contractor HY/2009/19, no major noisy construction works were conducted at the concerned location during the recorded period. As the exceedance is non-continuous, the exceedances were considered to be contributed by nearby IEC traffic and nearby non- CWB Projects.





After checking with contractor HY/2009/19, no construction activities were conducted at the concerned location during the recorded period. The exceedances were considered to be contributed by nearby IEC traffic.

After checking with contractor HY/2009/19, no major noisy construction activities were conducted at the concerned location during the recorded period. The exceedances were non-continuous and were considered to be contributed by nearby IEC traffic.