





Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with contractor HY/2009/19, socket H-piling was conducted during the recorded period, contractor mitigation measures including provision of temporary noise barrier were implemented while chilling system pipe work installation works (hammering and welding works) was conducting at the roof top of Hong Kong Electric Centre during the recorded period. As such, the exceedances were considered to be non-Project related and contributed by the pipe work installation works at Hong Kong Electric Centre.




Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with contractor HY/2009/19, bored piling was conducted during the recorded period, contractor mitigation measures including provision of temporary noise barrier were implemented. In view of the exceedances are non-continuous, the exceedances were considered to be non-Project related and contributed by nearby IEC traffic.



Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with Contractor HY/2009/19, no major noise generating construction activities were undertaken at the concerned location during the recorded period while breaking works and excavation works was observed at the construction site next to the monitoring station across February 2015. As such, the exceedances were considered to be non Project related and contributed by nearby non-CWB Project construction works.

After checking with contractor HY/2009/19, no construction activity was undertaken at the concerned location during the recorded period. The exceedances were considered to be contributed by pyrotechnic display during Chinese New Year.