





Graphic Presentation of Real Time Noise Monitoring Result (Food and Environmental Hygiene Department Depot)








Graphic Presentation of Real Time Noise Monitoring Result (Oil Street Community Liaison Center)






Graphic Presentation of Real Time Noise Monitoring Result (Food and Environmental Hygiene Department Depot)



After checking work activities of contractors HY/2009/17 and HY/2009/19, it was found that no works were being performed during monitoring. Exceedances were not continuous in which contributed by traffic noise at Island Eastern Corridor.

Graphic Presentation of Real Time Noise Monitoring Result (Oil Street Community Liaison Centre)




After checking work activities of contractor HY/2009/19, it was found that no works were being performed during monitoring. Exceedances were considered to be contributed by traffic noise at Island Eastern Corridor.

After checking work activities of contractor HY/2009/19, it was found that no major noisy activities were being performed. Exceedances were considered to be contributed by demolition works near the Oil Street Community Liaison Centre.




Graphic Presentation of Real Time Noise Monitoring Result (Food and Environmental Hygiene Department Depot)





Graphic Presentation of Real Time Noise Monitoring Result (Oil Street Community Liaison Center)



After checking work activities of contractor HY/2009/19, it was found that no major noisy activities were being performed. Exceedances were considered to be contributed by demolition works near the Oil Street Community Liaison Centre.