



Ref. No.	Date	Time	Location	Measured TSP Level	Unit	Action Level	Limit Level	Follow-up action
1hr TSP Exceedance at CMA1b on 8 November 2019								
X_19A002	8-Nov-19	10:55	CMA1b- Harbour Grand Hotel Boundary Wall	400.6	1 hr TSP (ug/m ³)	320.1	500	<p>Possible reason: Elevated TSP level in relate to local ambient condition around monitoring station</p> <p>Action taken / to be taken: Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p>Remarks / Other Obs: No construction works was undertaken on the monitoring date at around monitoring station CMA1b under Contractor of HY/2009/19 and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent monitoring on 14 November 2019.</p>
1hr TSP Exceedance at CMA1b on 8 November 2019								
X_19A003	8-Nov-19	10:55	CMA1b- Harbour Grand Hotel Boundary Wall	400.6	1 hr TSP (ug/m ³)	320.1	500	<p>Possible reason: Elevated TSP level in relate to local ambient condition around monitoring station</p> <p>Action taken / to be taken: Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p>Remarks / Other Obs: No construction works was undertaken on the monitoring date at around monitoring station CMA1b under Contractor of HY/2011/08 and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent monitoring on 14 November 2019.</p>
1hr TSP Exceedance at CMA3a on 8 November 2019								
X_19A004	8-Nov-19	10:49	CMA3a- CWB PRE office	407.1	1 hr TSP (ug/m ³)	311.3	500	<p>Possible reason: Elevated TSP level in relate to local ambient condition around monitoring station</p> <p>Action taken / to be taken: Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p>Remarks / Other Obs: No construction works was undertaken on the monitoring date at around monitoring station CMA3a under Contractor of HY/2010/08 and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent monitoring on 14 November 2019.</p>
1hr TSP Exceedance at CMA3a on 8 November 2019								
X_19A005	8-Nov-19	10:49	CMA3a- CWB PRE office	407.1	1 hr TSP (ug/m ³)	311.3	500	<p>Possible reason: Elevated TSP level in relate to local ambient condition around monitoring station</p> <p>Action taken / to be taken: Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p>Remarks / Other Obs: Pavement reinstatement works were undertaken on the monitoring date at around monitoring station CMA3a under Contractor of HK/2009/02 and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent monitoring on 14 November 2019.</p>



Ref. No.	Date	Time	Location	Measured TSP Level	Unit	Action Level	Limit Level	Follow-up action
1hr TSP Exceedance at CMA4a on 8 November 2019								
X_19A006	8-Nov-19	10:41	CMA4a- SPCA	332.8	1 hr TSP (ug/m ³)	311.3	500	<p>Possible reason: Elevated TSP level in relate to local ambient condition around monitoring station</p> <p>Action taken / to be taken: Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p>Remarks / Other Obs: Pavement reinstatement works were undertaken on the monitoring date at around monitoring station CMA4a under Contractor of HK/2009/02 and no particular observation regarding air quality impact was observed during sampling. Meanwhile, non WDII-CWB Project construction activities was observed opposite to the monitoring station on the monitoring date. In view of the above, the exceedance was considered to be not related to the Project works under Contract HK/2009/02 and potentially contributed by nearby non WDII-CWB Project construction activities. No exceedance was recorded in the subsequent monitoring on 14 November 2019.</p>