



| Ref. No. | Date | Time | Location | Construction Noise Level | Unit | Action Level | Limit Level | Follow-up action |
|----------|-----------|-------|---|--------------------------|-------------|---|-------------|--|
| X_10N134 | 9-Jul-13 | 13:45 | M6 - HK Baptist Church Henrietta Secondary School | 73 | Leq(30-min) | when one documented complaint was received. | 70 | <p>Possible reason: Traffic nearby and external renovation at City Garden was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.</p> <p>Remarks / Other Obs: Road works on IEC for Contract HY/2009/19 was conducted during the measurement. It was observed that traffic noise and external renovation works conducted at City Garden were major noise contribution during the monitoring period. It is concluded that the exceedance was not due to project.</p> |
| X_10N135 | 16-Jul-13 | 15:50 | M6 - HK Baptist Church Henrietta Secondary School | 72 | Leq(30-min) | when one documented complaint was received. | 70 | <p>Possible reason: Traffic nearby was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.</p> <p>Remarks / Other Obs: Installation of formwork and falsework for Contract HY/2009/19 was conducted during the measurement. It was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.</p> |