



Ref. No.	Date	Time	Location	Measured TSP Level	Unit	Action Level	Limit Level	Follow-up action
X_16A004	27-Aug-16	13:00	CMA1b- Oil Street Site Office	393.7	1 hr TSP (ug/m <sup>3</sup> )	320.1	500	<p><b>Possible reason:</b> Elevated TSP level in relate to local ambient condition around monitoring station</p> <p><b>Action taken / to be taken:</b> Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p><b>Remarks / Other Obs:</b> No construction works was undertaken on the monitoring date at around Oil Street Site Office under Contractor of HY/2009/19, dust suppression measure including haul road maintained in dampened condition was implemented and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition.</p>
X_16A005	27-Aug-16	13:00	CMA1b- Oil Street Site Office	393.7	1 hr TSP (ug/m <sup>3</sup> )	320.1	500	<p><b>Possible reason:</b> Elevated TSP level in relate to local ambient condition around monitoring station</p> <p><b>Action taken / to be taken:</b> Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p><b>Remarks / Other Obs:</b> Only formboard erection and rebar fixing works were undertaken on the monitoring date at around Oil Street Site Office while the haul road around the concerned location was hard paved and no particular observation regarding air quality impact was observed during sampling. In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition.</p>