Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action	
X_18N012		10:00	M1a-Footbridge at Ex Harbour Road Sports Centre	81	Leq(30min)	when one documented complaint was received.	75	Possible reason: Action taken / to be taken: Remarks / Other Obs:	Non WDII-CWB excavation works and hammering immeidately next to the monitoring station was observed as the major noise contribution during monitoring. A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. No construction work was conducted by Contract HK/2009/01 around the concerned location during the time of measurement while excavation works and hammering were conducted under non-WDII-CWB contractor next to the monitoring station and observed as the major noise contribution during monitoring monitoring monitoring monitoring was not contribution during monitoring monitoring monitoring monitoring station and observed as the major noise contribution during monitoring monit
									contractor next to the monitoring station and observed as the major noise contribution of As such, the exceedance was considered as non-Project related to Contract HK/2009/0

Ref. N	o. Date		Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action	
X_18	N011 2-F	Feb-18	10:00	M1a-Footbridge at Ex Harbour Road Sports Centre	81	Leq(30min)	when one documented complaint was received.	75	Possible reason:	Non WDII-CWB excavation works and hammering immeidately next to the monitoring station was observed as the major noise contribution during monitoring.
									Action taken / to be taken: Remarks / Other Obs:	A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. Despite trench excavation work was conducted by Contract HK/2009/02 around the concerned location during the time of measurement, no major noise emanation from the works was observed during monitoring. Meanwhile, excavation works and hammering were conducted under non-WDII-CWB contractor next to the monitoring station and observed as the major noise contribution during monitoring. As such, the exceedance was considered as not relate to Project works under HK/2009/02.