

Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action	
X_16N067	16-May-17	13:48	M1a-Harbour Road Sports Centre	76	Leq(30min)	when one documented complaint was received.	75	Possible reason:	Breaking and drilling next to the monitoring statoin under non WDII-CWB Contractor was observed as the major noise contribution.
						leceived.		Action taken / to be taken: Remarks / Other Obs:	A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. No construction work under EP-376/2009 was conducted by Contract HK/2012/08 around the concerned location during the time of measurement while breaking and drilling next to the monitoring statoin under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N070	25-May-17	10:45	M1a-Harbour Road Sports Centre	77	Leq(30min)	when one documented complaint was received.	75	Possible reason:	Bored piling works next to the monitoring statoin under non WDII-CWB Contractor was observed as the major noise contribution.
								Action taken / to be taken:	A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure.
								Remarks / Other Obs:	No construction work under EP-376/2009 was conducted by Contract HK/2012/08 around the concerned location during the time of measurement while bored piling works next to the monitoring statoin under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.