

Wan Chai Development Phase II – Central – Wan Chai Bypass at Wan Chai West Contract No. HK/2012/08

Silt Curtain Deployment Plan

for FEP-06/356/2009

Revision	Date of Issue	Remarks	Prepared by	Checked by
0	22 Apr 2013	First Issue	James MA	George CHEUNG
1	8 May 2013	Revised as per ET's and IEC's comments	James MA	George CHEUNG
2	23 Jul 2013	Revised as per EPD's comments and ET's comments	James MA	George CHEUNG
3	25 Nov 2015	Revised to reflect final stage of works arrangement	James MA	Keith TSE
4	13 Jan 2016	Revised as per EPD's comments	James MA	Keith TSE

This document contains confidential information of China State – Leader Joint Venture and shall not be copied or amended without the approval of the Contractor's Representative



Table of Content

Section

- 1 Introduction
- 2 Area of Application
- 3 Current Situation
- 4 Use of Material
- 5 Silt Curtain Installation Methodology
- 6 Silt Curtain Removal
- 7 Inspection and Rectification Works

Appendices

Appendix I	Layout Plan and Details of Silt Curtain
Appendix II	Material Catalogue of Silt Curtain
Appendix III	Programme for Major Marine Works
Appendix IV	Silt Curtain Daily Inspection Checklist
Appendix V	Site Photos



1 Introduction

Wan Chai Development Phase II – Central - Wan Chai Bypass at Wan Chai West (Contract No. HK/2012/08) is part of the permanent reclamation works including associated dredging works in Wan Chai Development Phase II (WDII) and Central - Wan Chai Bypass covered under the Environmental Permit No. EP-356/2009.

China State – Leader Joint Venture was granted on 5 March 2013 a Further Environmental Permit (No. FEP-06/356/2009) for the Contract No. HK/2012/08 under the master Environmental Permit.

Under Condition 2.8 of Part C of the FEP-06/356/2009, a silt curtain deployment plan has to be prepared and deposited by the permit holder to the EPD at least two weeks prior to the commencement of the marine works.

In the first three stages of the works, mainly dredging and seawall trench filling will be carried out. Both frame type and general type silt curtains will be deployed to prevent sediment plume dispersion arising from the works.

In the final stage of works (i.e. both the dredging and seawall trench filling stages are completed), only the silt curtain for culvert channel is deployed which serves as a general type silt curtain to prevent any potential discharge from the upstream outside the site boundary of the project.

The purpose of this Silt Curtain Deployment Plan is to show the implementation of deploying silt curtain in areas, in particular, around seawall dredging and seawall trench filling in reclamation shoreline zones during construction phase of the project (Contract No. HK/2012/08) which is undertaken by China State – Leader Joint Venture (CSLJV). CSLJV is responsible for the installation, maintenance, repairing (in case of damage) and removal of the silt curtain during the course of marine works until completion.

2 Area of Application

Silt curtain shall be provided during dredging and seawall trench filling works which may affect the water quality around the site. To restrict the dispersion of sediment plume during the dredging and seawall trench filling works, woven geotextile shall be used as the silt curtain system that is sustained by floating



foam and operated in such a way that tidal rise and fall can be accommodated.

Two types of silt curtain will be deployed:

- (A) Frame type silt curtain to closely enclose the dredging areas during closed grab dredging;
- (B) General type silt curtain to surround the dredging areas and the seawall trench filling areas.

In dredging stage, one frame type silt curtain will be deployed to closely enclose the dredging areas for prevention of sediment plume dispersion during the closed grab dredging.

One general type silt curtain will be deployed to enclose the dredging areas for prevention of sediment plume dispersion arising from the transfer of dredged materials between the grab frame and pontoon. The pontoon with bunker will be moored along the dredger and the silt curtains. Dredged materials in the bunker will be transferred to the hopper barge via the crane of a derrick lighter. Tarpaulin sheeting will be installed when necessary among the hopper barge, derrick barge and pontoon to prevent marine deposit from dropping into the sea.

In seawall trench filling stage, one general type silt curtain will be deployed to enclose the works areas for prevention of sediment plume dispersion arising from the transfer of rockfill from the grab to the seawall trench.

In the final stage of works (i.e. both the dredging and seawall trench filling stages are completed), only the silt curtain for culvert channel will be deployed which serves as a general type silt curtain to prevent any potential discharge from the upstream outside the site boundary of the project. (refers to drawing for final stage of works and photo for silt curtain for culvert channel in Appendix I). There will be no marine traffic entering/leaving the culvert channel. To suit the site condition with reference to the tidal range, the silt curtain would be extended as closely as practicable to the seabed level. The inspection and rectification for this silt curtain will generally follow the procedures in Section 7.

The layout plan and the details for deployment of silt curtains during different



stages of works and its general arrangement is shown in Appendix I. The programme for major marine works is shown in Appendix III. To suit the site condition with reference to the tidal range, the silt curtain would be extended as closely as practicable to the seabed level. The condition of ballast steel chain would be checked regularly to maintain the extension of silt curtain as closely as practicable to the seabed level.

3 Current Situation

Both the dredging and seawall trench filling are completed as of November 2015. No marine plant for dredging and seawall trench filling is necessary for the project and there is no chance of any source of pollution arising from the works as used to be contained by both the frame type and general type silt curtains. Please refer to the site photos in Appendix V.

In the final stage of works (i.e. both the dredging and seawall trench filling stages are completed), only the silt curtain for culvert channel is deployed which serves as a general type silt curtain to prevent any potential discharge from the upstream outside the site boundary of the project. There will be no significant impact on the water quality despite minor remaining marine works including installation of berm stones, seawall blocks and coping being carried out.

4 Use of Material

"Bonar SG110/110" woven geotextile, manufactured by BONTEC, is proposed as the silt curtain system for this Project. Catalogue of the material is shown in Appendix II. BONTEC is operated in accordance with an ISO 9001:2000 quality assurance system and ISO 14001 environmental management system to provide a good quality product. The Bonar geotextile is widely used in recent port works construction projects such as CV/2003/06 — Stanley Waterfront Improvement Project, CV/2004/02 — Reconstruction of Wong Shek and Ko Lau Wan Public Piers, CV/2002/04 — Penny's Bay Reclamation Stage 2 and HK12/02 — CED Central Reclamation Phase III, Engineering Works (Please refer to Appendix II). The properties of Bonar geotextile are satisfactory and fulfill the requirements as stipulated in the particular specification. Visual inspection of the silt curtain shall be carried out on a daily basis.

According to the "Assessment and Remediation of Contaminated Sediments Program" of United States Environmental Protection Agency, silt curtain has



been used at many locations with varying degrees of success. Moreover, the successful experiences in the deployment of the material "Bonar SG110/110" woven geotextile as silt curtain have been demonstrated in many projects as listed above. According to the Environmental Monitoring and Audit Manual, regular monitoring of water quality shall be carried out by the Environmental Team for complying with the statutory regulation and maintaining the quality of marine water during the course of construction.

5 Silt Curtain Installation Methodology

5.1 General Type Silt Curtain

- a. Link up 300mm buoys together by a net
- b. Tie the top end of the geotextile to the buoys net and the bottom end with steel chain ballast before transportation
- c. Transport the silt curtain to the location for fixing via a marine pontoon.
- d. Workers tie the buoy to nearby existing structures with nylon ropes.
- e. Put the buoys to the water and then slowly put the geotextile with the steel chain ballast into sea.
- f. In order to maintain the position of the silt curtain especially at the locations with strong current, place concrete sinkers to the seabed if required and tie the silt curtain to the sinkers with nylon strings by divers.

5.2 Frame Type Silt Curtain

- a. Prefabricate a 15m x 12m rectangular shape floating steel frame using 400mm diameter x 8mm thick steel circular hollow sections.
- b. Tie the top end of the geotextile to the steel frame by nylon strings / steel wires.
- c. Tie the bottom end of the geotextile with ballast steel chain. This arrangement shall maintain the geotextile in vertical position during the course of the dredging.
- d. Place and unfold the silt curtain to the sea by grab dredger. Fix the floating steel frame alongside the grab dredger with a movement joint. Slowly put the geotextile together with the ballast steel chain to the sea.
- e. The frame shall enclose the dredged area to ensure water quality impact is minimized.
- f. Prepare different length of the geotextile for replacement in order to suit



the various existing seabed levels.

6 Silt Curtain Removal

After completion of the marine works, the silt curtain shall be removed as follows:

- a. Prior to decommission of silt curtain, make sure all marine works or works affecting the seawall shall be completed, and also the water quality shall be checked to ensure no dispersion of muddy water outside the works areas.
- b. Loosen the fixing wire of the silt curtain from the concrete block and remove the silt curtain by motor boat for general type silt curtain or by crane for frame type silt curtain.
- c. Lifting the concrete block slightly by diver team and crane boat in order to minimize the disturbance of seabed causing mud wave.

7 Inspection and Rectification Works

Inspection and rectification works will be carried out for the silt curtain as follows and recorded in the silt curtain daily inspection checklist as shown in Appendix IV:

- a. Diver inspection shall be carried out to inspect the installation and decommission of silt curtain to ensure proper installation and functioning of the silt curtain according to the design drawings.
- b. During the entire construction period, visual inspection and regular diver inspection shall be carried out to ensure no muddy water passing through the silt curtain system and to maintain proper functioning of the silt curtain. Visual inspection for the silt curtain shall be carried out daily. When damaging is suspected during daily inspection, diver inspection would be undertaken in order to ensure the performance of the silt curtain is effective and efficient. If the silt curtain is damaged and repairing works are necessary, all dredging work should stop at once until the damaged silt curtain is fixed. The silt curtain will then be lifted up by grab dredger / derrick barge. A new piece of geotextile with sufficient overlapping length (1m) will be attached to the existing silt curtain. If the extent of the damaged is large and silt curtain cannot be lifted up without causing further damage, a new layer of silt curtain will be installed from sea level to seabed




and the damaged location on two sides will be covered for a minimum of 5m. The dredging works will resume after repairing of the damaged silt curtains.


- c. The site foreman shall supervise the entire installation and decommissioning processes. He shall also closely monitor the effectiveness of the silt curtain and report any irregularities which may affect its proper functioning so as to trigger early rectification by the Contractor.
- d. In case of any malfunction of the silt curtain, diver inspection shall be carried out to check whether there is any damage or defect of the silt curtain and the situation will be immediately reported to the Environmental Team. Once the damage or defect is found, the rectification works shall be carried out to maintain well-functioning of the silt curtain under the supervision of the site foreman.
- e. 20 linear meters of additional geotextile will be made ready for use and be kept on site for emergency replacement in case of damage or defect of the silt curtain is observed.




Appendix I

Layout Plan and Details of Silt Curtain



















Photo of Silt Curtain for Culvert Channel for Final Stage of Works











TYPICAL DETAILS FOR SILT CURTAIN

DEPLOYMENT

CONTRACT NO. HK/2012/08 WAN CHAI DEVELOPMENT PHASE II — CENTRAL — WAN CHAI BYPASS AT WAN CHAI WEST

TITLE


DETAILS OF SILT CURTAIN (GENERAL TYPE)

> 中國建築一利達聯營 CHINA STATE - LEADER JOINT VENTURE

DRG. NO.

HK_2012_08/CDB/SK/00034

SCALE	DATE OF DRAWING ISSUE	
N.T.S.	23-JUL-2013	
DIMENSIONS ARE IN MILLIMETRE	COPYRIGHT RESERVED	



Contract No. HK/2012/08 Wan Chai Development Phase II – Central – Wan Chai Bypass at Wan Chai West Silt Curtain Deployment Plan



Appendix II

Material Catalogue of Silt Curtain

bontec

a bonar technical fabrics product



SG 110/110

Woven polypropylene geotextile made of slit film tapes


Technical data sheet according to internal specifications Bonar TF: version 06 dd. 05/01/10

Accompanying documents CE marking: version 04 dd. 05/01/10

CE

1137-CPD-615

10



	test method	value	tolerance	
Mechanical properties				
Tensile strength MD	FALICO 40940	110,0 kN/m	-9,9 kN/m	
Tensile strength CD	EN ISO 10319	110,0 kN/m	-9,9 kN/m	
Elongation MD	Elitica conde	12,0 %	+/-2,8 %	
Elongation CD	EN ISO 10319	8,0 %	+/-1,8 %	
Static puncture resistance – CBR	EN ISO 12236	12,50 kN	-2,50 kN	
Oynamic perforation resistance - cone drop	EN ISO 13433	10,0 mm	+2,0 mm	
Hydraulic properties				
Nater permeability normal to the plane	mileo «veća	25x10-3 m/s	-8x10-3 m/s	
Vater flow normal to the plane (*)	EN ISO 11058	25 Vm².s	-8 ¥m².s	
Characteristic opening size (AOS)	EN ISO 12956	230,0 µm	+/-69,0 µm	
Physical properties				
hickness under 2 kPa (*)	EN ISO 9863-1	1,53 mm	+/-0,31 mm	
Veight (*)	EN ISO 9864	464,0 g/m²	+/-46,4 g/m²	
illionerstammensionen, validakskiligistysetistorilaisen. – processori osi osi osi osi osi osi osi osi osi os	100 % polypropylene w	100 % polypropylené woven geotextile		
Durability		predicted to be durable for a minimum of 25 years in natural soll with 4 < pH < 9 and soil temperatures < 25° C		

roads	railways	foundations & retaining walls	drainage systems	erosion control systems
EN 13249:2000	EN 13250:2000	EN 13251:2000	EN 13252:2000	EN 13253:2000
2	¥		2. Millionnallin	
reservoirs & dams	canals	Tunnels & under- ground structures	solid waste	liquid waste
EN 13254:2000	EN 13255:2000	EN 13256:2000	EN 13257:2000	EN 13265:2000

- 1. This geolectile is intended for use in both functions & applications highlighted with a bold border.
- 2. It is the responsibility of all users to satisfy themselves that the above data is current.
- 3. Roll dimensions are $5.25\,\mathrm{m}\times100\,\mathrm{m}$. Other dimensions on demand.
- 4. Bonar Technical Fabrics reserves the right to alter product specifications without prior notice.
- 5. Although not guaranteed, these results do to the best of our knowledge offer a true and accurate record of the product's performance.
- 6. Boner Technical Fabrics cannot accept responsibility for the performance of these products as the conditions of use are beyond our control.
- 7. Geotextile has to be covered within 2 weeks after installation
- (*) Not mendated characteristics for CE marking.





G AND E COMPANY LIMITED

Room B, 13/F Cheung Lee Industrial Bldg. 9 Cheung Lee Street Chai Wan, Hong Kong Tel: 2508 0058

Fax: 2570 0089

website: www.g-and-e.com

July 9, 2010

OFFICIAL ANNOUNCEMENT

I would like to inform you that geotextile Bontec SG100/100 is upgraded to SG110/110 effective immediately, and that SG100/100 has become obsolete. The performance of SG110/110 is superior to that of SG100/100.

No adjustment and adaptation are necessary to the current application, installation method, packaging and quality control assurance program with the improved properties of SG110/110.

Bonar Technical Fabrics is Europe's premier manufacturer of woven and nonwoven geotextile products, with continuous commitment to quality, product development and production improvement. One of Bonar's many advantages is that they are vertically integrated. This means they have their own fiber production which helps ensure consistent product performance. Bonar also has a high production capacity with the facility locates in close proximity to the Antwerp port. These translate into more efficient supply.

I have attached the manufacturer's letter here about the change for your reference. We would be happy to answer any questions that you may have.

Thank you for your kind attention.

Best regards

Gary Ng

Gary Ng General Manager

bontec

a bonar technical fabrics product

To: G and E - Hong Kong	From: Isabelle Ruyff	elaere - 0032 52 457 487	
Gary	Philippe Grimmelprez – 0032 52 457 486		
E mail: nannette@g-and-e.com	Pages: 1+		
Your reference: Bontec® SG 110/110			
	Our reference:	G&E07052010.doc	

Dear Gary,

We are pleased to confirm that the old name of the Bontec® SG100/100 has been replaced with the Bontec® SG 110/110.

Bonar constantly strives to increase the performance of the products over time. Thanks to improved polymers, extrusion and weaving techniques we managed to produce stronger geotextiles with the same unit weight. Hydraulic characteristics were not affected either.

Bonar uses very strict -in house- and ISO 9001:2000 quality and ISO 14001 environmental standards (in annex) and is using electricity generated from 100 % renewable sources.

We send hereby the newest datasheet as well for your information.

Should you require any further information, please do not hesitate to contact us. Best regards

Philippe Grimmelprez Global Sales & Marketing Manager



Bontec SG110/110 Woven Polypropylene Geotextile

Certification

QUALITY MANAGEMENT SYSTEM CERTIFICATE

ISO 9001: 2000

DIDID

DEME

The BQA, sa hereby declares that the quality management system of Bonar Technical Fabrics NV – Site in Zele en Lokeren



located at Industriestraat 39 - 9240 Zele - Belgium, has been examined on 05-05-2008 and found in conformity with the ISO 9001, edition 2000, standard for the following application field:

Development, manufacture and sales of a standard range of fibres and textiles such as agrotextiles, building textiles and geosynthetics, as well as similar products especially designed to customer specifications

This certificate has been issued by the BQA, sa according to its quality manual concerning the certification of quality systems, and after concluding the contract of certification N° DS/AJ/CER/05-05-2008/301, under which the company accepts a regular control of its quality management system.

Certificate Nº BQ4_QMS019_C_2004301 Valid until 04-05-2011



304 N° 019-QMS

Any person arvere of misuse of this certificate may address thanelf to the BQA, etc. This certificate may only be disclosed in its entirety. BQA, st - me Montoyer 24 (89) - 1000 Brussels.

IE C

D.SIMOENS

Directeur

CERTIFICATE OF ENVIRONNEMENTAL MANAGEMENT SYSTEM ISO 14001: 2004

)

The BQA, nv hereby declares that the environmental management system of the company Bonar Technical Fabrics NV – Site in Zele en Lokeren



미리미리미리미리미리미미미미

located at Industriestraat 39 – 9240 Zele - Belgtum, has been examined on 05-05-2008 and found in conformity with the ISO 14001, edition 2004, standard for the following application field:

Development, manufacture and sales of a standard range of fibres and textiles such as agrotexitles, building textiles and geosynthetics, as well as similar products especially designed to customer specifications.

This certificate has been tssued by BQA, nv according to its quality manual EMS concerning the certification of environmental management systems, and after the contract of certification Nº DS/AJ/CER-EMS/05-05-2008/84 under which the company accepts a regular control of its environmental management system.

Certificate Nº BOA_EMS019_C_200484 Valid until 04-05-2011

Marie Sand



미리미미미미미미

D. SIMOENS

Directeur

BOA Nº 019-EMS

Adry person arane of nione of this certificate may address binnelf to the BQA, nr. This certificate may only be disclosed in its entirely. The residence of this continue of the continue of t

States

DSAJICA112-07-2004





woven and non woven geotextiles

Zelc.05.10.09

CERTIFICATION OF COMFORMANCE

The undersigned supplier BONAR TECHNICAL FABRICS, hereby states under his responsibility that the following product complies with the indicated technical properties:

Invoice F0918342

Type

NW 9 525: 10500 m²

Type

NW 10 525 :18375 m2

Type Type NW 20 5250 : 10500 m1 SG 100/100 : 5250 m2

usulaur

Delivery does:


Packing list N. T0908524 and T0908557

Manufacturer: Bonar Technical Fabrics N.V.

BONAR TECHNICAL FABRICS N.V.

Bonar Technical Fabrics H.V

pie industripateage 39 6-9240 Zeje



12/08 2004 18:43 FAX 32 52 457495

BONAR TF GEO

@001/001

bontec

A benar technical fabrice product

Fax

Date: 11-Aug-04:
To: G and E - Hong Kong From: Isabelle Ruyffelaere - 0032 52 457 487
Mr. Gary NG Philippe Grimmelprez - 0032 52 457 486
Fax: Pages: 1 +
Your reference: Borner TF soquisition of Uco Technical Fabrics
Our reference: G&E11082004.fax

To Whom it may concern

We hereby confirm that Borner acquired the company <u>UCO Technical Fabrics</u> in October 1996 and all activities of the manufacturing and sales of Woven and Non woven geotextiles.

The Company changed name to BONAR TECHNICAL FABRICS.

its headquaters are moved to industriestrant 39, 9240 Zele, Belgium. At the same location is a new manufacturing plant of non woven geotextiles based.

The plant where woven geotextites are produced is based on the old UCO location: weverstaan 15, Lokeren, Belgium.

Should you require any further information, please do not healtate to contact us.

Best regards

Mippe Grimmelprez ales & Marketing Manager geotextiles.



BONAR Technical Fabrics marsa Industrientes 80: 8-8240 Zete - Belgium 78: 432 pp\$2 457 411 - 766, 452 pp\$2 457 496 E-mail secondicional com BONIAR Yapus & Fabrics Ltd.

S. Kapusur Stract - Dandes DID 783 - United Kingdom
Tal 444 (glysin 74916) - Fail 444 (glysin 241178
E-mail publications/published



Bontec SG110/110 Woven Polypropylene Geotextile

Installation Guideline

BONTEC: Woven and Non Woven Geotextiles manufactured by Bonar Technical Fabrics - Belgium.



RECOMMENDATION FOR THE INSTALLATION OF GEOTEXTILES

- The BONTEC geotextiles shall be kept in its original packaging in order to protect it from damaging UV-rays and high temperatures.
- The BONTEC geotextiles shall be stored protected from wind, rain, excess moisture or sunlight.
- The BONTEC geotextiles shall only be unpacked just before use. The material shall be covered within 1 week
- The BONTEC geotextiles shall be labelled and show the following data:
 - roll number
 - quality
 - name of the manufacturer
 - roll length & width
 - roll weight
- The BONTEC geotextiles shall be laid with the longitudenal ascis down slopes
- A minimum overlap of 500 mm between the different sheets shall be respected. Sewing of the different fabrics shall be done with a double prayer stitching technique with non deteriorating thread.
- Wherever visibility or installation of the BONTEC geotextile is poor an extra safety overlap of +/- 1 m shall be respected
- The surfaces to be covered with BONTEC geotextiles shall be smooth and free of sticks, roots, sharp objects, and all debris that may damage the fabric. The surface to be covered shall be firm and unyielding, with no sudden changes or brakes in grade.
- The compacted sub-base shall be maintained in a smooth, uniform and compacted condition during installation of the fabric.
- In area's where wind is prevalent, fabric installation shall be started at the upwind side of the project and proceed downwind. The leading edge of the fabric shall be secured at all times with sandbags or other means sufficient to hold it down during high winds. Sandbags or rubber tires may be used as required to hold the fabric in position during installation. Tires shall not have exposed teel cords or other sharp edges which may snag or cut the fabric. Materials, equipment or other items shall not be dragged across the fabric or be allowed to slide down slopes on the fabric.
- Should the fabric be damaged during any step of the installation, the damaged section shall be repaired by covering it with a piece of fabric which extends at least 0,6 meter in all directions beyond the damaged area. The fabric shall be secured as directed by the engineer.
- Smoking shall not be permitted by personnel working on the fabric.

P.geodiversen/installationgeot.doc



Bontec SG110/110 Woven Polypropylene Geotextile

List of Project Reference

Bonar

Date	Profest	Client	Comultant	Style:
Feb-05	CV/2003/06 Stanley Waterfront Improvement Project - Construction Pier and Boardwalk	Sun Fook Kong (Civil) Ltd	Civil Engineering and Development Department	
Feb-05	99/9028 Lamma Power Station	Wai Kee (Zens) Construction & Transportation Co Ltd	Maunsell Geotechnical Services Ltd	SG100/100
Feb-05	CV/2004/02 Reconst. of Wong Shek & Ko Lau Wan Public Piers	Kin Shing Construction Co Ltd	Civil Engineering and Development Department	\$G100/100
Apr-05	CV/2002/04 Penny's Bay Reclamation Stage 2	Gammon Skanska Ltd Shun Tat Construction Engineering Ltd	Scott Wilson Ltd	SG100/100 SG100/100
Apr-05	HK/12/02 CED, Central Reclamation Phase III, Engineering Works	Best Leader Engineering Ltd Leighton - China State - Van Oord Joint Venture	Atkins China Ltd	SG100/100 SG100/100
May-05	03/8013 Lamma Island to Cyberport	Leader Marine Contractors Ltd Honwin Engineering Ltd	Maunsell Geotechnical Services Ltd	SG100/100 SG100/100
Jul-05	Shenzhen to Tai Po Twin Submarine Gas Pipeline Project	Honwin Engineering Ltd		SG100/100
Sep-05	TP37/03 Remaining Engineering Infrastructure Works for Pak Shek Kok Development Package 2A	Leader - Wai Kee (C&T) Joint Venture	Hyder Consulting Ltd	SG100/100
Nov-05	HY/2002/26 Stone Cutter's Bridge	Hong Kong River Engineering Co Ltd	Ove Arup & Partners HK Ltd	SG100/100
Feb-06	CV/2005/12 Fill Reception Facilities at Tseung Kwan O Area 137 Quarry Bay and Mui Wo	Penta-Ocean Construction Co Ltd	Civil Engineering and Development Department	SG100/100
Mar-06	Maintenance Dredging at Castle Peak Power Station (CPPS) Jetty	Development Ltd	Civil Engineering and Development Department	SG100/100
Mar-06	CV/2004/04 Maintenance and Repairs to Government / Public Piers and Immersed Tubes of Hung Hom Cross- Harbor Tunnel	Co (Group)	Civil Engineering and Development Department	SG100/100
Mar-06	HY/2005/06 Castle Peak Road Improvement West of Tsing Lung Tau	2	Mouchel Halcrow JV	SG100/100 SG100/100

Мау-06	212 Main Works for the Proposed Third Golf Course Development at Kau Sai Chau, Sai Kung	China Harbour Englneering Co (Group)	Ove Arup & Partners HK Ltd	SG100/100
Jun-06	Hong Kong Convention and Exhibition Centre Project - Silt Screening for Intake Pipe	Wai Kee (Zens) Construction & Transportation Co Ltd Kaden - Wai Kee (C&T) Joint Venture	NA	SG100/100 SG100/100
Aug-06	EP/SP/52/06 Development of EcoPark in Tuen Mun Area 38	Kaden Construction Limited	Scott Wilson Ltd	\$G100/100
Sep-06	CV/2004/06 Management and Capping of Contaminated Mud Pit IV at East of Sha Chau - Phase III	Kaden - Wai Kee (C&T) Joint Venture	Civil Engineering and Development Department	SG100/100
Oct-06	Lamma Island Cable Landing	United Marine Co Ltd	Hong Kong Electric Co Ltd	SG100/100
Nov-06	CV/2004/01 Maintenance and Repairs to Seawalls, Piers and Other Port Works	Kin Shing Construction Co Ltd	Civil Engineering and Development Department	SG100/100
Dec-06	Private project	Friendly Benefit Engineering Ltd		SG100/100
Feb-07	Prebored Socketted H-Piles at Hong Kong Convention & Exhibition Centre	Yee Hop Engineering Co Ltd	NA	SG100/100
May-07	HY/2005/06 Castle Peak Road Improvement - West of Tsing Lung Tau	Chun Wo Construction & Engineering Co Ltd	Mouchel Halcrow JV	\$G100/100
May-07	CV/2004/05 Dredging Maintenance	China Harbour Engineering Co Ltd	Civil Engineering and Development Department	SG100/100
Aug-07	Dredging Project in Lai Chi Kok Shipyard	Maritime Mechanic Ltd	NA	\$G100/100
Aug-07	6/WSD/06 Construction of Salt Water Supply System for Penny's Bay	Univic Engineering Ltd	Water Supplies Department	\$G100/100
Nov-07	Permanent Aviation Fuel Facility Hong Kong International Airport (Contract No. H2104)	UDL Dredging Ltd	Babtie Asia Ltd	SG100/100
Dec-07	Seawall Modify, Tuen Mun Area 38	Cheer Engineering Ltd	Scott Wilson Ltd	SG100/100
May-08	DC/2007/10 Design and Construction of HK West Drainage Tunnel	Tapbo Civil Engineering Co Ltd	Ove Arup & Partners HK Ltd	SG100/100
Sep-08	CV/2006/05 Maintenance of Seawalls and Navigation Channels	China Harbour Engineering Co Ltd	Civil Engineering and Development Department	SG100/100

Sep-08 Marine Works at Maldives Kwan Sing Engineering & Construction SG100/100 Co.Ltd Nov-08 DC/2007/06 Kwan Lee Construction Co Ltd SG100/100 Maunsell Consultants River Improvement Works in Upper Lam Tsuen River, She Shan River and Asia Ltd Upper Tai Po River Mar-09 DC/2007/01 Shanghai Urban Construction Group Mott Connell Ltd SG100/100 Drainage Improvement Works in SG40/40 Corp Ki Lun Tsuen, Kwu Tung, Ma Tso Lung and Sha Ling SG100/100 Jun-09 CHEC247 China Harbour Engineering Co Ltd Lamma Power Station - Navigation Channel Improvement

Updated November 26, 2009



Bontec SG110/110 Woven Polypropylene Geotextile

Photo References



G AND E COMPANY LIMITED

Room B, 13/F Cheung Lee Industrial Building 9 Cheung Lee Street, Chai Wan, Hong Kong

Tel: 852-2508 0058 Fax: 852-2570 0089

website: www.g-and-e.com



Date

Feb-10

Project

Contract No. HY/2009/11

Central - Wanchai Bypass - North

Point Reclamation

Client

Highways Department

Consultant

AECOM

Main Contractor

China Habour Engineering Company

Works

Silt Curtain

Materials

Woven Geotextile SG100/100

Size

3,675 sgm



Bontec SG110/110 Woven Polypropylene Geotextile

Approval Letters

Civil Engineering and



土木工程底

Civil Engineering Office

Web stps

intro/www.codd.gov.hit

E-mali Telephone

式于那件 電話

(852) 2760 5737 : (852) 2714 2054

WX Our reference

! () in PW WC/CV0402/R20/340 Pt.1

Your reference 来面信託

: KS330/2005

香港九隆公主流101號 土木工程拓展者大權四統

4/F, Civil Engineering and Development Building. 101 Princess Margaret Road, Kowloon, Hong Kong

24 January 2005

BY MAIL & FAX No. 2780 2085

Kin Shing Construction Company Limited

27 Yin Chong Street,

Mone Kok Kowloon

(Attn.: Mr. Patrick P K Chan - Site Agent)

Dear Sirs,

Contract No. CV/2004/82 Reconstruction of Wong Shek and Ko Law Wan Public Piers

Material Submission - Geotextile for Silt Curtain

I refer to your letter of 14.1.2005 enclosing the particulars of the geotextile for fabrication of silt cortain.

In accordance with PS Clause 26.08(2), the proposed "SG 100/100" woven geotextile manufactured by Bonar Technical Fabrics is approved to be used under the captioned Contract.

Pursuant to PS Clause 26.08(1), you are required to submit details of the silt curtains 3 weeks before their deployment.

c.c. SIOW/P2B - Site Copy Yours faithfully,

(WHIEE) Engineer's Representative

Port Works Division Civil Engineering and Development Department

\$2360 P.001 /001

789.28.2005 17:33

FROM : G AND E COMPANY LIMITED

PHONE NO. : + 852 2570 0089

Apr. 28 2005 12:02PM P7

24-FEB-2005 19:57 FRON SFK

TD 25788889

土木工程業

Civil Engineering Office

著作儿童主公主任 100 新

上木工程和国際大樓《卷

Kewloon, Hong Kong

A/F, Civil Engineering and Development Building, 101 Princess Margaret Road,

18 February 2005

P. Rt./R1

16 % JOIGE

土木工程拓展署 Civil Engineering and Development Department

WH

: http://www.sedd.pov.hk

E-mail

#75#: **電器** 例及

1 (452) 2762 5035 (152) 2714 2054

Table To Table Ta

Sun Fook Kong (Civil) Limited Rms. 3207-10, Great Eagle Centre, 23 Harbour Road, Wan Chai,

Hong Kong (Atta: Mr. Howard KONG - Fax No.2827 6275)

Dear Six.

Contract No. CV/2003/06

Simpley Waterfront Improvement Project -Countraction of Pier and Boardwalk

Fabric for Silt Curtain

I refer to your above letters dated 21.1.2005 and 15.2.2005 proposing the SG100/100 fabric supplied by "Bonar Isolatical Fabrics" for sill contain.

I have no objection to your proposed material for silt curtain.

Yours faithfully.

Engineer's Representative Port Works Division

Civil Engineering and Development Department

ć.c. (Atta: SIOW/PIA) Site Office CEGIPIA

File PW WC/CV0306/M10/300

YIGHNE

2570004

TOTAL P.01

Mott MacDonald Hong Kong Limited

Consulting Engineers

Chief Resident Engineer's Office North Lantau Development - Tung Chung for Territories Development Department

Our Ref: S287/NL1/25.7/283/JY

30 June 1992

China Harbour Engineering Company 19/F, China Harbour Building 370-374 King's Road North Point Hong Kong.

Attn : Mr. S. Y. Yu

Dear Sirs,

North Lantau Development Contract No. NLI/91 Tung Chung Development Phase I - Site Formation Materials for Subsoil Drains

T.D.D. CONTRACT NO. M. 1/91 C. E. Dept.									
DATE	-	ACTION"	MPORM						
EA		7 mm	110						
DEA	laun-	,							
95			- 5						
			-1-2						
SUR	*								
FOREMAN									
L	water c								
		Fel 8 2							
FRE	- 1	111							

I refer to your letter ref. NL1/C/0097/008/MM/145 of 10/6/92 submitting materials for subsoil drains for our approval.

I have the following comments:

- The proposed subsoil drain material i.e. 300mm diameter ADS corrugated polyethylene subsoil drain pipes from Benpak Waterwise company is acceptable.
- 2) The proposed Geotextile SG17/15 from UCO (2 layers) as protection for subsoil drainage is acceptable in principal. Please submit further technical specification such as lapping and she storage requirements recommended by the manufacturer.
- 3) The proposed Greenfix Eromat Special type 5 from CCL is still under review. You will be notified of the outcome if a decision is made.

Yours faithfully

for MOTT MACDONALD HONG KONG LIMITED

Luke Chi

Engineer's Representative

LCJY/ak

Wi 3/16

Ø,

Maunsell Consultants Asia Ltd

8/F Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road Shatin, N.T. Hong Kong

茂盛(亞洲)工程顧問有限公司

香港新界沙田鄉事會路(38 點斯城市中央廣端第 2 座 8 楼

T +852 2605 8282 F +852 2691 2649 www.maunsell.aeccm.com SRE's Office T +852 2669 0708 F +852 2631 2889 E sre@ltriw.com.hk

Your Ref.: DC0706/M1.2/1512 & 1529

Our Ref. ; (DC/2007/06)/R20/106(0023)

Chiu Hing Construction & Transportation Co. Ltd. Room 201, 2/F Fuk Shing Commercial Building 28 On Lok Mun Street On Lok Tsuen, Fanling New Territories, Hong Kong

Attn: Mr. Roger Lau (Site Agent)

13 November 2008

Dear Sir.

Contract No. DC/2007/06 River Improvement Works in Upper Lam Tsuen River, She Shan River and Upper Tal Po River

Proposed Geolextile at Gabion Wall in She Shan River and Upper Taj Po River

I refer to your letter dated 7 November 2008 and 12 November 2008 respectively.

Please be advised that since the water flow rate of the proposed geotextile model Bontec SG100/100 meets the requirements in accordance with P.S. Clause 7.150, I have no further objections to your proposed use of woven geotextile model Bontec SG100/100, supplied by "G and E Company Ltd." at gabion wall in She Shan River and Tai Po River, subject to its satisfactory performance on site.

Yours faithfully.

Adrian Ng Resident Engineer

CO MCAL - Attn : Mr. Conder Yan

Chiu Hing H.O.

ANACION

Maunicell AECOM Stroup Chief Executive: T.C.K.Shuin President: D.D.S.Lo. Chief President Officer: P.K.L.Worp. Mauneell Consultants Asia Ltd. Chairman: F. S.Y. Bong, Managing Director: E.S.C. Ma. Essentive Directors: C.W.T. Wong, A.K.W.L., M.C. Peousin, S.A. Robinani, Mauneell Consultants Asia Ltd. Chairman: F. S.Y. Bong, Managing Director: E.S.C. Ma. Essentive Directors: C.W.T. Wong, A.K.W.L., P.A.Chec, T.K.S. Tang, F.S.X. Tang, F.S.X. Tang, A.Y. Kwok, A.R.F. Kwan, C.K.Lau, P.A.Chec, T.K.S. Tang, F.S.X. Tang, F.S.X. Tang, F.S.X. Tang, F.S.X. Tang, G.C. W.Ng, P.M. Cheef, K.H.X. Chong, I.M. Whiten, H.N.Y. Wong, J.Y.F. Chiu, Consultants: A Handlion, R.D. Taylor, Technical Directors: Y.Yarmassic, C.H.T. So., J.Y. Ling, G.C.W.Ng, P.M. Cheef, K.H.X. Chong, I.M. Whiten, H.N.Y. Wong, J.Y.F. Chiu, Consultants: A Handlion, R.D. Taylor, R.C. Cheng, P.Y. Coak, D.S.W. Leong, J.Y. Li. Office: Australia, Canada, China, Dermani, Egypt, Gaza, Greece, Hong Kong, Edila, Indonesia, Instant, Israel, Malaysia, Natherlands, Oman, Philippines, Poland, Puerio Rico, Romania, Cerpt, Singapore, South Kinea, Thaliand, United Areb Entrans, United Kingdom, United Status of America, Vistager.



Appendix III

Programme for Major Marine Works

Revision 2 Project: Wan Chai Development Phase II - Central - Wan Chai Bypass at Wan Chai West Month No. 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 May 2016 May 2014 May 2015 Area C EXISTING CAUSE SERVALL CON Area B Area C CRIII Area A2 Marine Work Zoning Plan Area A1 Area D Legend: Dredging Seawall Seawall Trench Programme for Major Marine Works Filling Start Date: May 2013



Appendix IV

Silt Curtain Daily Inspection Checklist



Contract No. HK/2012/08 Wan Chai Development Phase II Central – Wan Chai Bypass at Wan Chai West

隔泥幕每日檢查表 Silt Curtain Daily Inspection Checklist

隔泥幕	等名稱:							
地點:								
檢查E	日期及時間:							
項目	描述		情況		需要立即採取行動?*		預計修補日期	備註
1.	No any floating debris / refuse within silt curtain? 隔泥幕內沒有任何垃圾?	是	否	要		不要		
2.	Buoys in good condition? 浮泡情况良好?							
3.	Tying rope in good condition? 繫上的繩索情況良好?							
4.	Geotextile intact and in good condition? 土工布完整無缺?							
5.	Sinkers in good condition? 下墜物情況良好?							
6.	No any obstruction to water flow between geotextile? 土工布之間沒有任何阻礙水的流動?							
7.	Silt curtain frame in good condition? 隔泥幕鐵架狀況良好?							
			<u>.</u>	•				

檢查人:		
	中國建築 – 利達	_

Contract No. HK/2012/08 Wan Chai Development Phase II – Central – Wan Chai Bypass at Wan Chai West Silt Curtain Deployment Plan



Appendix V

Site Photos





Site towards the West on 19 Dec 2015



Site towards the East on 19 Dec 2015