



| Ref. No. | Date      | Time | Location   | Construction Noise Level, dB(A) | Parameter  | Action Level                                   | Limit Level dB(A) | Follow-up action  |
|----------|-----------|------|--|---------------------------------|------------|--|-------------------|---|
| X_21N001 | 18-Mar-21 | 8:44 | M6 - HK Baptist Church<br>Henrietta Secondary School | 67                              | Leq(30min) | when one documented<br>complaint was received. | 65                | <p>Possible reason: Traffic nearby was observed during monitoring and was considered as the major noise contribution.</p> <p>Action taken / to be taken: A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure.</p> <p>Remarks / Other Obs: No construction works was conducted under HY/2009/19 around the monitoring location and nearby traffic noise was observed as major noise source during monitoring. As such, the exceedance was considered as non-Project related.</p> |



| Ref. No.      | Date                      | Location                              | Parameter   | Construction Noise Level, dB(A) | Action Level                                | Limit Level dB(A) | Follow-up action   |
|---------------|---------------------------|---------------------------------------|-------------|---------------------------------|---|-------------------|--|
| RTN_2021.03_1 | 9, 10, 17 and 18 Mar 2021 | RTN 3 - Yu Lee Mo Fan Memorial School | Leq (30min) | Refer to Appendix 4.2           | When one documented complaint was received. | 75                | After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 around the monitoring station on 9, 10, 17 and 18 March 2021. As such, the exceedance was considered as non-Project related. |



| Ref. No.   | Date      | Time | Location                              | Measured TSP Level | Unit                           | Action Level | Limit Level | Follow-up action  |
|--|-----------|------|---------------------------------------|--------------------|--------------------------------|--------------|-------------|---|
| <b>24hr TSP Exceedance at CMA2a on 17 April 2021</b> |           |      |                                       |                    |                                |              |             |   |
| X_21A001   | 17-Apr-21 | 8:00 | CMA2a - Causeway Bay Community Centre | 209.8              | 24 hr TSP (ug/m <sup>3</sup> ) | 169.5        | 260         | <p><b>Possible reason:</b> Elevated TSP level in relate to local ambient condition around monitoring station</p> <p><b>Action taken / to be taken:</b> Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p><b>Remarks / Other Obs:</b> Removal of launching girder parts was undertaken on the monitoring date at around monitoring station CMA2a under Contractor of HY/2009/19 and no particular observation regarding air quality impact was observed during sampling.</p> <p>Meanwhile, elevated PM2.5 (Range from 8.5µg/m<sup>3</sup> to 47.5µg/m<sup>3</sup>) and PM10 (Ranged from 16.1µg/m<sup>3</sup> to 68.6µg/m<sup>3</sup>) level was recorded at EPD's Central/Western, Eastern General Station, Central Roadside Station and Causeway Bay Roadside Station. In addition, similar elevation in TSP level were recorded across the same period on 17 April 2021 at another AQM station at Central area (MA1b:201.1µg/m<sup>3</sup>), while no construction work was carried out around.</p> <p>In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent 1hr TSP monitoring on 19 April 2021. Nevertheless, the Contractor of HY/2009/19 was reminded to maintain regularly dust suppression measures for any potential dusty surface and dust generating operation around the concerned location to avoid any potential cumulative air quality impact.</p> |
| <b>24hr TSP Exceedance at MA1b on 17 April 2021</b>  |           |      |                                       |                    |                                |              |             |   |
| X_21A002   | 17-Apr-21 | 8:00 | MA1b - Harbour Building               | 201.1              | 24 hr TSP (ug/m <sup>3</sup> ) | 173.4        | 260         | <p><b>Possible reason:</b> Elevated TSP level in relate to local ambient condition around monitoring station</p> <p><b>Action taken / to be taken:</b> Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's working procedures.</p> <p><b>Remarks / Other Obs:</b> No construction works was undertaken on the monitoring date at around monitoring station MA1b under Contractor of HY/2009/19 and no particular observation regarding air quality impact was observed during sampling.</p> <p>Meanwhile, elevated PM2.5 (Range from 8.5µg/m<sup>3</sup> to 47.5µg/m<sup>3</sup>) and PM10 (Ranged from 16.1µg/m<sup>3</sup> to 68.6µg/m<sup>3</sup>) level was recorded at EPD's Central/Western, Eastern General Station, Central Roadside Station and Causeway Bay Roadside Station.</p> <p>In view of the above, the action level exceedance was considered to be non-project related and contributed by local ambient condition. No exceedance was recorded in the subsequent 1hr TSP monitoring on 19 April 2021.</p>  |



| Ref. No.      | Date                                 | Location                              | Parameter   | Construction Noise Level, dB(A) | Action Level                                | Limit Level dB(A) | Follow-up action  |
|---------------|--------------------------------------|---------------------------------------|-------------|---------------------------------|---|-------------------|---|
| RTN_2021.05_1 | 5, 6, 11, 12, 13, 17 and 21 May 2021 | RTN 3 - Yu Lee Mo Fan Memorial School | Leq (30min) | Refer to Appendix 5.4           | When one documented complaint was received. | 75                | After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 around the monitoring station on 5, 6, 11, 12, 13, 17 and 21 May 2021. As such, the exceedance was considered as non-Project related. |