

TISCH ENVIRONMENTAL, INC. 145 SOUTH MIAMI AVE VILLAGE OF CLEVES, OH 45002 513.467.9000 877.263.7610 TOLL FREE 513.467.9009 FAX

# ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

Date - May 20, 2016 Rootsmeter S/N 0438320 Ta (K) - Operator Tisch Orifice I.D 3166 Pa (mm) - 74										
PLATE OR Run # 1 2 3 4 5	VOLUME START (m3)  NA NA NA NA NA	VOLUME STOP (m3) NA NA NA NA NA	DIFF VOLUME (m3)  1.00 1.00 1.00 1.00	DIFF TIME (min)  1.4270 1.0220 0.9100 0.8730 0.7180	METER DIFF Hg (mm) 3.2 6.4 7.9 8.8 12.7	ORFICE DIFF H2O (in.) 2.00 4.00 5.00 5.50 8.00				

## DATA TABULATION

Vstd	(x axis) Qstd	(y axis)		Va	(x axis) Qa	(y axis)
0.9967 0.9925 0.9904 0.9892 0.9840	0.6985 0.9711 1.0883 1.1332 1.3705	1.4150 2.0010 2.2372 2.3464 2.8299		0.9957 0.9915 0.9893 0.9882 0.9830	0.6977 0.9701 1.0872 1.1320 1.3691	0.8851 1.2517 1.3995 1.4678 1.7702
Qstd slor intercept coefficie y axis =	(b) = ent (r) =	2.10714 -0.05158 0.99978 	 [a)]	Qa slope intercept coefficie y axis =	(b) =	1.31946 -0.03226 0.99978

# CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]

Qa = Va/Time

For subsequent flow rate calculations:

Qstd =  $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ Qa =  $1/m\{[SQRT H2O(Ta/Pa)] - b\}$ 



TISCH ENVIRONMENTAL, INC. 145 SOUTH MIAMI AVE VILLAGE OF CLEVES, OH 45002 513.467.9000 877.263.7610 TOLL FREE 513.467.9009 FAX

# ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

		Orifice I.I		438320 0005	Ta (K) - Pa (mm) -	293 - 759.46
PLATE OR Run #	VOLUME START (m3)	VOLUME STOP (m3)	DIFF VOLUME (m3)	DIFF TIME (min)	METER DIFF Hg (mm)	ORFICE DIFF H2O (in.)
1 2 3 4 5	NA NA NA NA NA	NA NA NA NA NA	1.00 1.00 1.00 1.00 1.00	1.3960 0.9970 0.8910 0.8500 0.6990	3.2 6.4 7.8 8.7 12.7	2.00 4.00 5.00 5.50 8.00

# DATA TABULATION

Vstd	(x axis) Qstd	(y axis)		Va	(x axis) Qa	(y axis)
1.0120 1.0078 1.0058 1.0047 0.9993	0.7249 1.0108 1.1288 1.1820 1.4296	1.4257 2.0163 2.2543 2.3643 2.8514		0.9958 0.9916 0.9896 0.9885 0.9832	0.7133 0.9946 1.1107 1.1630 1.4066	0.8784 1.2423 1.3889 1.4567
Qstd slop intercept coefficie	t (b) = ent (r) =	2.02533 -0.03593 0.99983	n e n	Qa slope intercept coefficie	t (b) = ent (r) =	1.26823 -0.02214 0.99983
y axis =	SQRT[H20(I	Pa/760)(298/5	Γa)]	y axis =	SQRT[H20(	[a/Pa)]

# CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)

Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]

Qa = Va/Time

For subsequent flow rate calculations:

Qstd =  $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ 

 $Qa = 1/m\{[SQRT H2O(Ta/Pa)] - b\}$ 



Location	:	ACL1	Calibration Date :		21-Apr-17
Equipment no.	:	HVS014	Calibration Due Date :	_	21-Jun-17

# **CALIBRATION OF CONTINUOUS FLOW RECORDER**

Ambient Condition									
Temperature, T <sub>a</sub>	Temperature, T <sub>a</sub> 299 Kelvin Pressure, P <sub>a</sub> 1008 mmHg								
<u>-</u>									

Orifice Transfer Standard Information								
Equipment No.         Ori002         Slope, m <sub>c</sub> 2.10714         Intercept, bc         -0.05158								
Last Calibration Date	20-May-16	$(H \times P_a / 1013.3 \times 298 / T_a)^{1/2}$						
Next Calibration Date	20-May-17		= <i>m</i>	$_{c}$ $\times$ $Q_{std}$ + $b_{c}$				

	Calibration of TSP									
Calibration	Ма	nometer Re	eading	Q <sub>std</sub>	Continuous Flow	IC				
Point	н	H (inches of water)		(m <sup>3</sup> / min.)	Recorder, W	(W(P <sub>a</sub> /1013.3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)				
l	(up)	(down)	(difference)	X-axis	(CFM)	Y-axis				
1	1.4	1.4	2.8	0.8152	37	36.8413				
2	2.2	2.2	4.4	1.0157	44	43.8113				
3	3.4	3.4	6.8	1.2567	52	51.7770				
4	4.6	4.6	9.2	1.4578	55	54.7642				
5	5.7	5.7	11.4	1.6200	61	60.7384				
By Linear Regression of Y	on X	•								

By Linear	Regression	of	Υ	on X	
-----------	------------	----	---	------	--

14.2494 Slope, m 28.6579 Intercept, b =

Correlation Coefficient\* 0.9933

Yes/No\*\* Calibration Accepted

As per client's provided information, the equipment reference no. of the calibrated High Volume Sampler has been

re-assigned from EL550 to HVS014 with respect to the update in quality management system.

Calibrated by Jackey MA Checked by Pauline Wong 21-Apr-17 21-Apr-17 Date Date

<sup>\*</sup> if Correlation Coefficient < 0.990, check and recalibration again.



Location	:	ACL1	Calibration Date	:	16-Jun-17
Equipment no.	:	HVS014	Calibration Due Date	:	16-Aug-17

# CALIBRATION OF CONTINUOUS FLOW RECORDER

Ambient Condition									
Temperature, T <sub>a</sub>	Temperature, T <sub>a</sub> 302 Kelvin Pressure, P <sub>a</sub> 1005 mmHg								
- "									

Orifice Transfer Standard Information									
Equipment No.         Ori001         Slope, m <sub>c</sub> 2.02533         Intercept, bc         -0.03593									
Last Calibration Date	20-Mar-17	$(HxP_a/1013.3x298/T_a)^{1/2}$							
Next Calibration Date	20-Mar-18		= <i>m</i>	$c \times Q_{std} + b_c$					

Calibration of TSP								
Calibration	Ма	nometer Ro	eading	Q <sub>std</sub>	Continuous Flow	IC		
Point	н	inches of	water)	(m <sup>3</sup> / min.)	Recorder, W	(W(P <sub>a</sub> /1013.3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)		
	(up)	(down)	(difference)	X-axis	(CFM)	Y-axis		
1	1.1	1.1	2.2	0.7422	36	35.6140		
2	2.0	2.0	4.0	0.9946	41	40.5604		
3	3.2	3.2	6.4	1.2534	49	48.4747		
4	4.1	4.1	8.2	1.4165	54	53.4211		
5	5.3	5.3	10.6	1.6080	60	59.3567		
By Linear Regression of Y o	By Linear Regression of Y on X							
	Slope, m	=	27.86	663 Ir	ntercept, b = 13.	9633		
Correlation C	oefficient*	=	0.99	63				

By Linear Regression of Y on X					
Slope, m	=	27.8663	Intercept, b =	13.9633	
Correlation Coefficient*	=	0.9963			
Calibration Accepted	=	Yes/No**			
	_				

Calibrated by	:	Jackey MA	Checked by :	Pauline Wong
Date	:	16-Jun-17	Date :	16-Jun-17

<sup>\*</sup> if Correlation Coefficient < 0.990, check and recalibration again.



Location	: _	ACL2a	Calibration Date	:	21-Apr-17
Equipment no.	:	HVS011	Calibration Due Date	:	21-Jun-17

# CALIBRATION OF CONTINUOUS FLOW RECORDER

Ambient Condition						
Temperature, T <sub>a</sub>	299	Kelvin	Pressure, P <sub>a</sub>	1008	mmHg	

Orifice Transfer Standard Information								
Equipment No.	Ori002	Slope, m <sub>c</sub>	2.10714	Intercept, bc	-0.05158			
Last Calibration Date	20-May-16	$(HxP_a/1013.3x298/T_a)^{1/2}$						
Next Calibration Date	20-May-17		= <i>m</i>	$_{c}$ $\times$ $Q_{std} + b_{c}$				

Calibration of TSP							
Calibration	Mai	nometer Re	eading	Q <sub>std</sub>	Continuous Flow	IC	
Point	Н (	inches of v	water)	(m <sup>3</sup> / min.)	Recorder, W	(W(P <sub>a</sub> /1013.3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)	
	(up)	(down)	(difference)	X-axis	(CFM)	Y-axis	
1	1.5	1.5	3.0	0.8429	29	28.8757	
2	2.3	2.3	4.6	1.0380	36	35.8456	
3	3.7	3.7	7.4	1.3099	44	43.8113	
4	4.8	4.8	9.6	1.4886	50	49.7856	
5	6.3	6.3	12.6	1.7018	54	53.7685	
By Linear Regression of Y	on X						
	Slope, m	=	29.40	059 Int	tercept, b =	4.8879	
Correlation C	oefficient*	=	0.99	56			
Calibration Accepted =		Yes/P	<del>\0</del> **				

* if Correlation Coefficient < 0.99	<ol><li>check and recalibration again.</li></ol>
-------------------------------------	--

Remarks : As per client's provided information, the equipment reference no. of the calibrated High Volume Sampler has been

re-assigned from EL111 to HVS011 with respect to the update in quality management system.

 Calibrated by
 :
 Jackey MA
 Checked by
 :
 Pauline Wong

 Date
 :
 21-Apr-17
 Date
 :
 21-Apr-17



Location	:	ACL2a	Calibration Date	:	16-Jun-17
Equipment no.	:	HVS011	Calibration Due Date	: -	16-Aug-17

# CALIBRATION OF CONTINUOUS FLOW RECORDER

Ambient Condition						
Temperature, T <sub>a</sub>	302	Kelvin	Pressure, P <sub>a</sub>	1005	mmHg	

Orifice Transfer Standard Information								
Equipment No.	Ori001	Slope, m <sub>c</sub>	2.02533	Intercept, bc	-0.03593			
Last Calibration Date	20-Mar-17	$(HxP_a/1013.3x298/T_a)^{1/2}$						
Next Calibration Date	20-Mar-18	$m_c \times Q_{std} + b_c$						

	Calibration of TSP								
Calibration	Mai	nometer Re	eading	Q <sub>std</sub>	Continuous Flow	IC			
Point	Н (	inches of v	vater)	(m <sup>3</sup> / min.)	Recorder, W	(W(P <sub>a</sub> /1013.3x298/T <sub>a</sub> ) <sup>1/2</sup> /35.31)			
	(up)	(down)	(difference)	X-axis	(CFM)	Y-axis			
1	1.5	1.5	3.0	0.8638	30	29.6784			
2	2.4	2.4	4.8	1.0879	36	35.6140			
3	3.7	3.7	7.4	1.3465	42	41.5497			
4	4.8	4.8	9.6	1.5312	50	49.4639			
5	5.9	5.9	11.8	1.6956	56	55.3996			
By Linear Regression of Y	on X								
	Slope, m	=	30.68	393 Int	tercept, b =	2.2921			
Correlation Coefficient*		=	0.99	27		_			
Calibration	Calibration Accepted =		Yes/P	<del></del>					

<ul> <li>if Correlation Coefficient &lt; 0.990, check and recalibration a</li> </ul>	gain.
--	-------

Remarks : As per client's provided information, the equipment reference no. of the calibrated High Volume Sampler has been

re-assigned from EL111 to HVS011 with respect to the update in quality management system.

 Calibrated by
 :
 Jackey MA
 Checked by
 :
 Pauline Wong

 Date
 :
 16-Jun-17
 Date
 :
 16-Jun-17



# 綜 合 試 驗 有 限 公 司

香港黄竹坑道37號利達中心12樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



# CERTIFICATE OF CALIBRATION

Certificate No.:

16CA0805 02

Page

οf

Item tested

Description: Manufacturer: Type/Model No.: Sound Level Meter (Type 1) B & K 2250-L 3006790

Microphone B&K 4950 2827240

B & K ZC0032 21213

Adaptors used:

Item submitted by Customer Name:

Serial/Equipment No.:

Lam Geotechnics Ltd.

Address of Customer:

Request No.:

Date of receipt:

05-Aug-2016

Date of test:

08-Aug-2016

### Reference equipment used in the calibration

Description:

Multi function sound calibrator

Model: B&K 4226

Serial No. 2288444

Expiry Date: 18-Jun-2017 18-Apr-2017

Traceable to: CIGISMEC CEPRE

Signal generator Signal generator DS 360 DS 360 33873 61227

18-Apr-2017

CEPRE

# **Ambient conditions**

Temperature:

Relative humidity: Air pressure:

21 ± 1 °C 60 + 10 %

1000 ± 5 hPa

# Test specifications

- The Sound Level Meter has been calibrated in accordance with the requirements as specified in BS 7580: Part 1: 1997 and the lab calibration procedure SMTP004-CA-152.
- 2. The electrical tests were performed using an electrical signal substituted for the microphone which was removed and replaced by an equivalent capacitance within a tolerance of ±20%.
- The acoustic calibration was performed using an B&K 4226 sound calibrator and corrections was applied for the difference between the free-field and pressure responsess of the Sound Level Meter.

### Test results

This is to certify that the Sound Level Meter conforms to BS 7580; Part 1: 1997 for the conditions under which the test was performed.

Details of the performed measurements are presented on page 2 of this certificate.

eng Jun Qi

Actual Measurement data are documented on worksheets.

Huang Jian

Approved Signatory:

Date:

09-Aug-2016

Company Chop:

Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

Soils & Materials Engineering Co., Ltd.

Form No.CARP152-1/Issue 1/Rev.C/01/02/2007



# 綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港黃竹坑道37號利達中心12樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com Tel: (852) 2873 6860 Fax: (852) 2555 7533



2

# CERTIFICATE OF CALIBRATION

(Continuation Page)

16CA0805 02

Page

(

1, Electrical Tests

The electrical tests were performed using an equivalent capacitance substituted for the microphone. The results are given in below with test status and the estimated uncertainties. The "Pass" means the result of the test is inside the tolerances stated in the test specifications. The "-" means the result of test is outside these tolerances.

Test:	Subtest:	Status:	Expanded Uncertanity (dB)	Coverage Factor
1691.	Juniest.	otatus.	and the state of t	
Self-generated noise	Α	Pass	0.3	
	С	Pass	0.8	
	Lin	Pass	1.6	
Linearity range for Leg	At reference range , Step 5 dB at 4 kHz	Pass	0.3	
	Reference SPL on all other ranges	Pass	0.3	
	2 dB below upper limit of each range	Pass	0.3	
	2 dB above lower limit of each range	Pass	0.3	
Linearity range for SPL	At reference range , Step 5 dB at 4 kHz	Pass	0.3	
Frequency weightings	Α	Pass	0.3	
. , , ,	С	Pass	0.3	
	Lin	Pass	0.3	
Time weightings	Single Burst Fast	Pass	0.3	
• •	Single Burst Slow	Pass	0.3	
Peak response	Single 100µs rectangular pulse	Pass	0.3	
R.M.S. accuracy	Crest factor of 3	Pass	0.3	
Time weighting I	Single burst 5 ms at 2000 Hz	Pass	0.3	
	Repeated at frequency of 100 Hz	Pass	0.3	
Time averaging	1 ms burst duty factor 1/103 at 4kHz	Pass	0.3	
3 2	1 ms burst duty factor 1/104 at 4kHz	Pass	0.3	
Pulse range	Single burst 10 ms at 4 kHz	Pass	0.4	
Sound exposure level	Single burst 10 ms at 4 kHz	Pass	0.4	
Overload indication	SPL	Pass	0.3	
	Leq	Pass	0.4	

### 2, Acoustic tests

The complete sound level meter was calibrated on the reference range using a B&K 4226 acoustic calibrator with 1000Hz and SPL 94 dB. The sensitivity of the sound level meter was adjusted. The test result at 125 Hz and 8000 Hz are given in below with test status and the estimated uncertainties.

Test:	Subtest	Status	Expanded Uncertanity (dB)	Coverage Factor
Acoustic response	Weighting A at 125 Hz	Pass	0.3	
·	Weighting A at 8000 Hz	Pass	0.5	

# 3, Response to associated sound calibrator

N/A

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

Calibrated by:

Date:

End

Checked by:

| Fung Chi Yip | Cam Tze Wai | 08-Aug-2016 | Date: 09-Aug-2016

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP152-2/Issue 1/Rev.C/01/02/2007



# 綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港黃竹坑道37號利達中心12樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com Tel: (852) 2873 6860 Fax: (852) 2555 7533



# CERTIFICATE OF CALIBRATION

Certificate No.:

16CA1117 01-02

Page:

of

2

Item tested

Description:

Acoustical Calibrator (Class 1)

Manufacturer:

Rion Co., Ltd. NC-73

Type/Model No.: Serial/Equipment No.:

NC-73 10707358

Adaptors used:

-

Item submitted by

Curstomer:

Lam Geotechnics Ltd.

Address of Customer:

-

Request No.: Date of receipt:

17-Nov-2016

Date of test:

18-Nov-2016

# Reference equipment used in the calibration

Description: Lab standard microphone Preamplifier Measuring amplifier	Model:	Serial No.	Expiry Date:	Traceable to:
	B&K 4180	2412857	14-Apr-2017	SCL
	B&K 2673	2239857	28-Apr-2017	CEPREI
	B&K 2610	2346941	26-Apr-2017	CEPREI
Signal generator	DS 360	61227	18-Apr-2017	CEPREI
Digital multi-meter	34401A	US36087050	18-Apr-2017	CEPREI
Audio analyzer	8903B	GB41300350	19-Apr-2017	CEPREI
Universal counter	53132A	MY40003662	19-Apr-2017	CEPREI

# Ambient conditions

Temperature:

23 ± 1 °C

Relative humidity:

50 ± 10 %

Air pressure:

1005 ± 5 hPa

### Test specifications

- The Sound Calibrator has been calibrated in accordance with the requirements as specified in IEC 60942 1997 Annex B
  and the lab calibration procedure SMTP004-CA-156.
- 2, The calibrator was tested with its axis vertical facing downwards at the specific frequency using insert voltage technique.
- The results are rounded to the nearest 0.01 dB and 0.1 Hz and have not been corrected for variations from a reference pressure of 1013.25 hectoPascals as the maker's information indicates that the instrument is insensitive to pressure changes.

### **Test results**

This is to certify that the sound calibrator conforms to the requirements of annex B of IEC 60942: 1997 for the conditions under which the test was performed. This does not imply that the sound calibrator meets IEC 60942 under any other conditions.

Details of the performed measurements are presented on page 2 of this certificate.

Min/Feng Jun Qi

Huang Jian

Approved Signatory:

Date:

21-Nov-2016

Company Chop:

Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP156-1/Issue 1/Rev.D/01/03/2007



# 綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

香港黃竹坑道37號利達中心12樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



# CERTIFICATE OF CALIBRATION

(Continuation Page)

Certificate No.:

16CA1117 01-02

2

#### 1, Measured Sound Pressure Level

The output Sound Pressure Level in the calibrator head was measured at the setting and frequency shown using a calibrated laboratory standard microphone and insert voltage technique. The results are given in below with the estimated uncertainties.

(Output level in dB re 20 μPa) Frequency Output Sound Pressure Measured Output Estimated Expanded Shown Level Setting Sound Pressure Level Uncertainty Hz dB dB dB 1000 94.00 94.12 0.10

#### 2. Sound Pressure Level Stability - Short Term Fluctuations

The Short Term Fluctuations was determined by measuring the maximum and minimum of the fast weighted DC output of the B&K 2610 measuring amplifier over a 20 second time interval as required in the standard. The Short Term Fluctuation was found to be:

At 1000 Hz

STF = 0.002 dB

Estimated expanded uncertainty

0.005 dB

#### 3, **Actual Output Frequency**

The determination of actual output frequency was made using a B&K 4180 microphone together with a B&K 2673 preamplifier connected to a B&K 2610 measuring amplifier. The AC output of the B&K 2610 was taken to an universal counter which was used to determine the frequency averaged over 20 second of operation as required by the standard. The actual output frequency at 1 KHz was:

At 1000 Hz

Actual Frequency = 991.6 Hz

Estimated expanded uncertainty

0.1 Hz

Coverage factor k = 2.2

#### **Total Noise and Distortion** 4,

For the Total Noise and Distortion measurement, the unfiltered AC output of the B&K 2610 measuring amplifier was connected to an Agilent Type 8903 B distortion analyser. The TND result at 1 KHz was:

At 1000 Hz

TND = 0.6 %

Estimated expanded uncertainty

0.7 %

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

Calibrated by:

End

Date:

Fung Chi Yir

18-Nov-2016

Checked by:

Date:

Lam Tze Wai 21-Nov-2016

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP156-2/Issue 1/Rev C/01/05/2005



# 綜 合 試 驗 有 限 公 司 SOILS & MATERIALS ENGINEERING CO., LTD.

港 黄 竹 坑 道 3 7 號 利 達 中 心 1 2 樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



# CERTIFICATE OF CALIBRATION

Certificate No.:

17CA0320 03

Page:

of

2

Item tested

Description:

Acoustical Calibrator (Class 1)

Manufacturer: Type/Model No.: Larson Davis CAL 200

Serial/Equipment No.:

13098

Adaptors used:

Item submitted by

Curstomer:

Lam Environmental Service Ltd.

Address of Customer:

Request No.:

Date of receipt:

20-Mar-2017

Date of test:

23-Mar-2017

# Reference equipment used in the calibration

Description:	Model:	Serial No.	Expiry Date:	Traceable to:
Lab standard microphone	B&K 4180	2412857	14-Apr-2017	SCL
Preamplifier	B&K 2673	2239857	28-Apr-2017	CEPREI
Measuring amplifier	B&K 2610	2346941	26-Apr-2017	CEPREI
Signal generator	DS 360	61227	18-Apr-2017	CEPREI
Digital multi-meter	34401A	US36087050	18-Apr-2017	CEPREI
Audio analyzer	8903B	GB41300350	19-Apr-2017	CEPREI
Universal counter	53132A	MY40003662	19-Apr-2017	CEPREI

# **Ambient conditions**

Temperature:

21 ± 1 °C

Relative humidity:

60 ± 10 %

Air pressure:

1010 ± 5 hPa

### Test specifications

- 1, The Sound Calibrator has been calibrated in accordance with the requirements as specified in IEC 60942 1997 Annex B and the lab calibration procedure SMTP004-CA-156.
- 2. The calibrator was tested with its axis vertical facing downwards at the specific frequency using insert voltage technique.
- The results are rounded to the nearest 0.01 dB and 0.1 Hz and have not been corrected for variations from a reference pressure of 1013.25 hectoPascals as the maker's information indicates that the instrument is insensitive to pressure changes.

# Test results

This is to certify that the sound calibrator conforms to the requirements of annex B of IEC 60942: 1997 for the conditions under which the test was performed. This does not imply that the sound calibrator meets IEC 60942 under any other conditions.

Details of the performed measurements are presented on page 2 of this certificate.

Huang Jian Min/Feng Jun Qi

Approved Signatory:

Date:

24-Mar-2017

Company Chop:

Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP156-1/Issue 1/Rev.D/01/03/2007



# 綜 合 試 驗 有 限 公 司 SOILS & MATERIALS ENGINEERING CO., LTD.

港黄竹坑道37號利達中心12樓 12/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. E-mail: smec@cigismec.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



# CERTIFICATE OF CALIBRATION

(Continuation Page)

Certificate No.:

17CA0320 03

Page:

2

#### 1. Measured Sound Pressure Level

The output Sound Pressure Level in the calibrator head was measured at the setting and frequency shown using a calibrated laboratory standard microphone and insert voltage technique. The results are given in below with the estimated uncertainties

			(Output level in dB re 20 μPa)
Frequency Shown Hz	Output Sound Pressure Level Setting dB	Measured Output Sound Pressure Level dB	Estimated Expanded Uncertainty dB
1000	94.00	93.98	0.10

#### 2. Sound Pressure Level Stability - Short Term Fluctuations

The Short Term Fluctuations was determined by measuring the maximum and minimum of the fast weighted DC output of the B&K 2610 measuring amplifier over a 20 second time interval as required in the standard. The Short Term Fluctuation was found to be:

At 1000 Hz

STF = 0.002 dB

Estimated expanded uncertainty

0.005 dB

#### 3, **Actual Output Frequency**

The determination of actual output frequency was made using a B&K 4180 microphone together with a B&K 2673 preamplifier connected to a B&K 2610 measuring amplifier. The AC output of the B&K 2610 was taken to an universal counter which was used to determine the frequency averaged over 20 second of operation as required by the standard. The actual output frequency at 1 KHz was:

At 1000 Hz

Actual Frequency = 1000.2 Hz

Estimated expanded uncertainty

0.1 Hz

Coverage factor k = 2.2

#### 4, Total Noise and Distortion

For the Total Noise and Distortion measurement, the unfiltered AC output of the B&K 2610 measuring amplifier was connected to an Agilent Type 8903 B distortion analyser. The TND result at 1 KHz was:

At 1000 Hz

TND = 0.5 %

Estimated expanded uncertainty

0.7 %

The expanded uncertainties have been calculated in accordance with the ISO Publication "Guide to the expression of uncertainty in measurement", and gives an interval estimated to have a level of confidence of 95%. A coverage factor of 2 is assumed unless explicitly stated.

End

Calibrated by:

Checked by:

Fung Chi Yip

Date:

23-Mar-2017

24-Mar-2017

The standard(s) and equipment used in the calibration are traceable to national or international recognised standards and are calibrated on a schedule to maintain the required accuracy level.

© Soils & Materials Engineering Co., Ltd

Form No.CARP156-2/Issue 1/Rev.C/01/05/2005



# EQUIPMENT PERFORMANCE CHECK / CALIBRATION REPORT

Report No.

: HK1710303

**Project Name** 

EQUIPMENT PERFORMANCE CHECK/CALIBRATION REPORT

Date of Issue

08/05/2017

Customer Address

: LAM ENVIRONMENTAL SERVICES LIMITED

: 11/F., CENTRE POINT, 181-185 GLOUCESTER ROAD, WAN CHAI, HONG KONG

Calibration Job No. Test Item No.

HK1710303 : HK1710303-01

Test Item Details

**Test Item Description** Manufacturer

Sonde YSI

Model No.

Professional Plus 14E100105

Serial No. Performance Method

Checked according to in-house method CAL005

(References: Temperature (Section 6 of Intermational Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure), pH value

(APHA 21e 4500H:B), Salinity (Refer to Conductivity APHA 19e 2510B)

, Dissolved oxygen (APHA 19e 4500-O,C))

**Test Item Receipt Date Test Item Calibration Date**  26/04/2017 08/05/2017

- Notes: 1. This report shall not be reproduced, except in full, without prior approval from Pilot Testing Limited.
  - 2. Results relate to item(s) as received.
  - 3. ± indicates the tolerance limit
  - 4. N/A = Not applicable
  - 5. APHA American Public Health Association, American Water Works Association and Water Environment. Federation, Standard Methods for the Examination of Water and Wastewater, APHA-AWWA-WEF. USA

6. DO, pH, salinity and temperature performance check was conducted by Pilot Testing Limited.

7. Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.

Approved Signatory

Ms. Wong Po Yan, Pauline (Testing Engineer)

Issue Date:

08/05/2017



WORK ORDER:

HK1710303

DATE OF ISSUE:

08/05/2017

CLIENT:

LAM ENVIRONMENTAL SERVICES LIMITED

Equipment Type	Sonde	
Manufacturer	YSI	
Model No.	Professional Plus	
Serial No.	14E100105	
Date of Calibration	08-May-17	
Date of next Calibation	08-Aug-17	

### Parameters:

Temperature (Method Ref: Section 6 of International Accreditation New Zealand Technical

Guide No.3 Second edition March 2008: Working Thermometer Calibration Procedure)

Reference Reading (°C)	Display Reading (°C)	Deviation (°C)
5.0	5.1	0.1
14.2	14.1	-0.1
23.8	23.4	-0.4
T	olerance Limit	±2.0

pH Value (Method Ref: APHA21e, 4500H:B)

Expected Reading (pH unit)	Reference Reading (pH unit)	Display Reading (pH unit)	Deviation (pH unit)
4.0	3.88	3.84	-0.04
7.0	6.95	6.88	-0.07
10.0	9.91	9.94	0.03
	Tolerance Limit		±0.20

Conductivity (Method Ref: APHA 19e, 2510)

KCI concentration (mol/L)	Reference Reading (ms/cm)	Display Reading (ms/cm)	Deviation (%)
0.0000	0.00	0.00	
0.1000	13.3	13.2	-0.75
0.2000	24.3	23.9	-1.65
0.5000	57.3	56.5	-1.40
	Tolerance Limit		±2.0

Dissolved Oxygen (DO) (Method Ref: APHA 19e, 4500-O, C)

Reference DO reading (mg/L)	DO reading od DO probe (mg/L)	Deviation (mg/L)
7.95	8.10	0.15
6.30	6.25	-0.05
5.61	5.53	-0.08
	Tolerance Limit	±0.20

### Remarks:

- (1) Maxium tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.
- (2) Displayed reading presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.
- (3) Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.



### EQUIPMENT PERFORMANCE CHECK / CALIBRATION REPORT

Report No. : HK1710208

Project Name : EQUIPMENT PERFORMANCE CHECK/CALIBRATION REPORT

Date of Issue : 17/03/2017

Customer : LAM GEOTECHNICS LIMITED

Address : 11/F., CENTRE POINT, 181-185 GLOUCESTER ROAD, WAN CHAI, HONG KONG

 Calibration Job No.
 : HK1710208

 Test Item No.
 : HK1710208-01

Test Item Details

Test Item Description : Sonde Manufacturer : YSI

 Model No.
 : Professional Plus

 Serial No.
 : 14M100277

Performance Method : Checked according to in-house method CAL005

(References: Temperature (Section 6 of Intermational Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure), pH value

(APHA 21e 4500H:B), Salinity (Refer to Conductivity APHA 19e 2510B)

, Dissolved oxygen (APHA 19e 4500-O.C))

Test Item Receipt Date : 15/03/2017 Test Item Calibration Date : 17/03/2017

Notes: 1. This report shall not be reproduced, except in full, without prior approval from Pilot Testing Limited.

2. Results relate to item(s) as received.

3. ± indicates the tolerance limit

4. N/A = Not applicable

 APHA - American Public Health Association, American Water Works Association and Water Environment Federation, Standard Methods for the Examination of Water and Wastewater, APHA-AWWA-WEF, USA

6. DO, pH, salinity and temperature performance check was conducted by Pilot Testing Limited.

 Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.

Approved Signatory

Issue Date:

17/03/2017

Ms. Wong Po Yan, Pauline (Testing Engineer)



WORK ORDER: HK1710208 DATE OF ISSUE: 17/03/2017

CLIENT: LAM GEOTECHNICS LIMITED

Equipment Type	Sonde	
Manufacturer	YSI	
Model No.	Professional Plus	
Serial No.	14M100277	
Date of Calibration	17-Mar-17	
Date of next Calibation	17-Jun-17	

### Parameters:

Temperature (Method Ref: Section 6 of International Accreditation New Zealand Technical Guide No.3 Second edition March 2008: Working Thermometer Calibration Procedure)

Reference Reading (°C)	Display Reading (°C)	Deviation (°C)
6.3	6.4	0.1
14.6	14.6	0.0
21.1	20.7	-0.4
	olerance Limit	±2.0

pH Value (Method Ref: APHA21e, 4500H:B)

Expected Reading (pH unit)	Reference Reading (pH unit)	Display Reading (pH unit)	Deviation (pH unit)
4.0	3.96	4.08	0.12
7.0	6.91	7.06	0.15
10.0	9.99	9.80	-0.19
11.20.75	Tolerance Limit		±0.20

Conductivity (Method Ref: APHA 19e, 2510)

KCI concentration (mol/L)	Reference Reading (ms/cm)	Display Reading (ms/cm)	Deviation (%)
0.0000	0.00	0.00	
0.1000	11.92	11.85	-0.59
0.2000	22.90	22.74	-0.70
0.5000	54.20	53.40	-1.48
	Tolerance Limit		±2.0

Dissolved Oxygen (DO) (Method Ref: APHA 19e, 4500-O, C)

Reference DO reading (mg/L)	DO reading od DO probe (mg/L)	Deviation (mg/L)
8.85	8.68	-0.17
6.24	6.36	0.12
5.70	5.85	0.15
	Tolerance Limit	±0.20

Remarks:

- (1) Maxium tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.
- (2) Displayed reading presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.
- (3) Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.



### EQUIPMENT PERFORMANCE CHECK / CALIBRATION REPORT

Report No.

: HK1710300

Project Name

: EQUIPMENT PERFORMANCE CHECK/CALIBRATION REPORT

Date of Issue

: 26/04/2017

Customer

: LAM ENVIRONMENTAL SERVICES LIMITED

Address

: 11/F., CENTRE POINT, 181-185 GLOUCESTER ROAD, WAN CHAI, HONG KONG

Calibration Job No. Test Item No.

HK1710300 : HK1710300-01

**Test Item Details Test Item Description** 

Sonde

Manufacturer

YSI

Model No. Serial No.

Professional Plus 16H100298

Performance Method

Checked according to in-house method CAL005

(References: Temperature (Section 6 of Intermational Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure), pH value

(APHA 21e 4500H:B), Salinity (Refer to Conductivity APHA 19e 2510B)

Dissolved oxygen (APHA 19e 4500-O,C))

**Test Item Receipt Date Test Item Calibration Date**  24/04/2017 25/04/2017

- Notes: 1. This report shall not be reproduced, except in full, without prior approval from Pilot Testing Limited.
  - 2. Results relate to item(s) as received.
  - 3. ± indicates the tolerance limit
  - 4. N/A = Not applicable
  - 5. APHA American Public Health Association, American Water Works Association and Water Environment Federation, Standard Methods for the Examination of Water and Wastewater, APHA-AWWA-WEF. USA

6. DO, pH, salinity and temperature performance check was conducted by Pilot Testing Limited.

7. Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.

Approved Signatory

Issue Date:

26/04/2017

Ms. Wong Po Yan, Pauline (Testing Engineer)



WORK ORDER:

HK1710300

DATE OF ISSUE:

26/04/2017

CLIENT:

LAM ENVIRONMENTAL SERVICES LIMITED

Equipment Type	Sonde	
Manufacturer	YSI	
Model No.	Professional Plus	
Serial No.	16H100298	
Date of Calibration	25-Apr-17	
Date of next Calibation	25-Jul-17	

# Parameters:

Temperature (Method Ref: Section 6 of Intermational Accreditation New Zealand Technical

Guide No.3 Second edition March 2008: Working Thermometer Calibration Procedure)

Reference Reading (°C)	Display Reading (°C)	Deviation (°C)
5.7	5.9	0.2
14.0	14.1	0.1
23.0	22.6	-0.4
	olerance Limit	±2.0

pH Value (Method Ref: APHA21e, 4500H:B)

Expected Reading (pH unit)	Reference Reading (pH unit)	Display Reading (pH unit)	Deviation (pH unit)
4.0	4.15	4.21	0.06
7.0	7.17	7.35	0.18
10.0	10.21	10.31	0.10
	Tolerance Limit		±0.20

Conductivity (Method Ref: APHA 19e, 2510)

KCl concentration (mol/L)	Reference Reading (ms/cm)	Display Reading (ms/cm)	Deviation (%)
0.0000	0.00	0.00	
0.1000	12.6	12.6	0.00
0.2000	23.8	23.8	0.00
0.5000	57.0	56.5	-0.88
	Tolerance Limit		±2.0

Dissolved Oxygen (DO) (Method Ref: APHA 19e, 4500-O, C)

Reference DO reading (mg/L)	DO reading od DO probe (mg/L)	Deviation (mg/L)
7.90	7.93	0.03
6.92	6.95	0.03
5.83	5.87	0.04
	Tolerance Limit	±0.20

Remarks:

- (1) Maxium tolerance and calibration frequency stated in the report, unless otherewise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.
- (2) Displayed reading presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.
- (3) Because of high sensitivity and ease of measurement, the conductivity method (according to APHA 19e 2510) is used to determine salinity.



Information supplied by customer:

CONTACT:

MR. SAM LAM

WORK ORDER: HK1710287

CLIENT:

LAM GEOTECHNICS LIMITED

DATE OF ISSUE: 21/4/2017

DATE RECEIVED: 20/4/2017

ADDRESS:

11/F, CENTRE POINT, 181-185, GLOUCESTER ROAD,

WANCHAI, HONG KONG

PROJECT:

METHOD OF PERFORMANCE CHECK/ CALIBRATION:

Ref: APHA22nd ed 2130B

### COMMENTS

It is certified that the item under performance check/calibration has been calibrated/checked by corresponding calibrated equipment in the laboratory.

Maximum Tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.

Scope of Test:	Turbidity	
Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1309192	
Equipment No.:	***	
Date of Calibration:	20/04/2017	

Remarks:

This is the Final Report. Results apply to sample(s) as submitted. All pages of this report have been checked and approved for release.

Approved Signatory:

Issue Date:

21/4/2017

Ms. Wong Po Yan, Pauline Testing Engineer



WORK ORDER: HK1710287 DATE OF ISSUE: 21/4/2017

CLIENT: LAM GEOTECHNICS LIMITED

Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1309192	
Equipment No.:		
Date of Calibration:	20/04/2017	
Date of next Calibation:	20/07/2017	

# Parameters:

Turbidity

Method Ref: APHA 22nd ed. 2130B

Expected Reading (NTU)	Display Reading (NTU)	Tolerance	
0	0.00		
4	3.88	-3.0%	
10	10.3	2.9%	
40	41.0	2.5%	
100	98.0	-2.0%	
400	400	0.0%	
1000	1000	0.0%	
	Tolerance Limit (±)	10%	

Remark: "Displayed Reading" presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.



Information supplied by customer:

CONTACT:

MR. SAM LAM

WORK ORDER: HK1710202

CLIENT:

LAM GEOTECHNICS LIMITED

DATE RECEIVED: 14/3/2017 DATE OF ISSUE: 15/3/2017

ADDRESS:

11/F, CENTRE POINT, 181-185, GLOUCESTER ROAD,

WANCHAI, HONG KONG

PROJECT:

# METHOD OF PERFORMANCE CHECK/ CALIBRATION:

Ref: APHA22nd ed 2130B

### COMMENTS

It is certified that the item under performance check/calibration has been calibrated/checked by corresponding calibrated equipment in the laboratory.

Maximum Tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.

Scope of Test:	Turbidity	
Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1512036	
Equipment No.:		
Date of Calibration:	15/03/2017	

This is the Final Report. Results apply to sample(s) as submitted. All pages of this report have been checked and approved for release.

Approved Signatory:

Ms. Wong Po Yan, Pauline

Testing Engineer

Issue Date:

15/3/2017



WORK ORDER:

HK1710202

DATE OF ISSUE: 15/3/2017

CLIENT:

LAM GEOTECHNICS LIMITED

Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1512036	
Equipment No.:		
Date of Calibration:	15/03/2017	
Date of next Calibation:	15/06/2017	

# Parameters:

Turbidity

Method Ref: APHA 22nd ed. 2130B

Expected Reading (NTU)	Display Reading (NTU)	Tolerance	
0	0.00		
4	3.99	-0.2%	
10	9.70	-3.0%	
40	40.4	1.0%	
100	95.0	-5.0%	
400	404	1.0%	
1000	1000	0.0%	
	Tolerance Limit (±)	10%	

Remark: "Displayed Reading" presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.



Information supplied by customer:

CONTACT: MR. SAM LAM WORK ORDER: HK1710434

CLIENT:

LAM GEOTECHNICS LIMITED

DATE OF ISSUE:

DATE RECEIVED: 02/06/2017 06/06/2017

ADDRESS:

11/F, CENTRE POINT, 181-185, GLOUCESTER ROAD,

WANCHAI, HONG KONG

PROJECT:

### METHOD OF PERFORMANCE CHECK/ CALIBRATION:

Ref: APHA22nd ed 2130B

# COMMENTS

It is certified that the item under performance check/calibration has been calibrated/checked by corresponding calibrated equipment in the laboratory.

Maximum Tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.

Scope of Test:	Turbidity	
Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1512036	
Equipment No.:		
Date of Calibration:	05/06/2017	

# Remarks:

This is the Final Report. Results apply to sample(s) as submitted. All pages of this report have been checked and approved for release.

Approved Signatory:

Ms. Wong Po Yan, Pauline Assistant Laboratory Manager Issue Date:

06/06/2017



WORK ORDER: HK1710434 DATE OF ISSUE: 06/06/2017

CLIENT: LAM GEOTECHNICS LIMITED

Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1512036	
Equipment No.:	(****)	
Date of Calibration:	05/06/2017	
Date of next Calibation:	05/09/2017	

# Parameters:

Turbidity

Method Ref: APHA 22nd ed. 2130B

Expected Reading (NTU)	Display Reading (NTU)	Tolerance	
0	0.00		
4	4.01	0.2%	
10	9.87	-1.3%	
40	39.4	-1.5%	
100	101	0.6%	
400	400	0.0%	
1000	1000	0.0%	
	Tolerance Limit (±)	10%	

Remark: "Displayed Reading" presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.



Information supplied by customer:

CONTACT: MR. SAM LAM WORK ORDER: HK1710175

CLIENT:

LAM GEOTECHNICS LIMITED

DATE RECEIVED: 3/3/2017 DATE OF ISSUE: 6/3/2017

ADDRESS:

11/F, CENTRE POINT, 181-185, GLOUCESTER ROAD,

WANCHAI, HONG KONG

PROJECT:

### METHOD OF PERFORMANCE CHECK/ CALIBRATION:

Ref: APHA22nd ed 2130B

### COMMENTS

It is certified that the item under performance check/calibration has been calibrated/checked by corresponding calibrated equipment in the laboratory.

Maximum Tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.

Scope of Test:	Turbidity	
Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1408039	
Equipment No.:	1111	
Date of Calibration:	04/03/2017	

This is the Final Report. Results apply to sample(s) as submitted. All pages of this report have been checked and approved for release.

Approved Signatory:

Ms. Wong Po Yan, Pauline

Testing Engineer

Issue Date:

6/3/2017



WORK ORDER: HK1710175 DATE OF ISSUE: 6/3/2017

CLIENT: LAM GEOTECHNICS LIMITED

Equipment Type:	Turbidimeter	-5/11/4
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1408039	
Equipment No.:		
Date of Calibration:	04/03/2017	
Date of next Calibation:	04/06/2017	

# Parameters:

Turbidity

Method Ref: APHA 22nd ed. 2130B

Expected Reading (NTU)	Display Reading (NTU)	Tolerance	
0	0.00		
4	4.14	3.5%	
10	10.0	0.0%	
40	40.0	0.0%	
100	99.6	-0.4%	
400	380	-5.0%	
1000	1000	0.0%	
	Tolerance Limit (±)	10%	

Remark: "Displayed Reading" presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.



Information supplied by customer:

CONTACT:

MR. SAM LAM

WORK ORDER: HK1710432

CLIENT:

LAM GEOTECHNICS LIMITED

DATE RECEIVED: 02/06/2017 DATE OF ISSUE:

06/06/2017

ADDRESS:

11/F, CENTRE POINT, 181-185, GLOUCESTER ROAD,

WANCHAI, HONG KONG

PROJECT:

### METHOD OF PERFORMANCE CHECK/ CALIBRATION:

Ref: APHA22nd ed 2130B

### COMMENTS

It is certified that the item under performance check/calibration has been calibrated/checked by corresponding calibrated equipment in the laboratory.

Maximum Tolerance and calibration frequency stated in the report, unless otherwise stated, the internal acceptance criteria of Pilot Testing Limited will be followed.

Scope of Test:	Turbidity	
Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1408039	
Equipment No.:		
Date of Calibration:	05/06/2017	

# Remarks:

This is the Final Report. Results apply to sample(s) as submitted. All pages of this report have been checked and approved for release.

Approved Signatory:

Ms. Wong Po Yan, Pauline Assistant Laboratory Manager Issue Date:

06/06/2017



WORK ORDER: HK1710432 DATE OF ISSUE: 06/06/2017

CLIENT: LAM GEOTECHNICS LIMITED

Equipment Type:	Turbidimeter	
Brand Name:	Xin Rui	
Model No.:	WGZ-3B	
Serial No.:	1408039	
Equipment No.:		
Date of Calibration:	05/06/2017	
Date of next Calibation:	05/09/2017	

# Parameters:

Turbidity

Method Ref: APHA 22nd ed. 2130B

Expected Reading (NTU)	Display Reading (NTU)	Tolerance	
0	0.00		
4	3.97	-0.7%	
10	9.98	-0.2%	
40	40.0	-0.1%	
100	101	1.3%	
400	400	0.0%	
1000	1000	0.0%	
	Tolerance Limit (±)	10%	

Remark: "Displayed Reading" presents the figures shown on item under calibration/checking regardless of equipment precision or significant figures.