


















# Graphic Presentation of Water Quality Result of WSD17 - Quarry Bay






















# Graphic Presentation of Water Quality Result of C5w - SHKC (Western)











# Graphic Presentation of Water Quality Result of WSD21 - Wan Chai











## Graphic Presentation of Water Quality Result of C1 - HKCEC
















# Graphic Presentation of Water Quality Result of C4w - WCT and GEC (Western)





### Graphic Presentation of Enhanced Water Monitoring Results (DO) at C6 - Excelsior Hotel







### Graphic Presentation of Enhanced Water Monitoring Results (DO) at C7 - Windsor House



**Graphic Presentation of Enhanced Water Monitoring Results (DO) at Ex-WPCWA SW  
- South-western corners of ex-Public Cargo Works Area**



**Graphic Presentation of Enhanced Water Monitoring Results (DO) at Ex-WPCWA SE  
- South-eastern corners of ex-Public Cargo Works Area**

