





Graphic Presentation of Water Quality Result of C1 - HKCEC









Remarks: Due to the blockage of road access to C1 on 15 Dec 2012 during mid-flood, the water quality monitoring was cancelled at C1 on 15 Dec 2012 during mid-flood.



Graphic Presentation of Water Quality Result of C2 - TH / APA / SOC















Graphic Presentation of Water Quality Result of C4w - WCT and GEC (Western)











Graphic Presentation of Water Quality Result of P3 - APA








Graphic Presentation of Water Quality Result of P1 - HKCEC Phase I










Graphic Presentation of Water Quality Result of P5 - WCT / RT / IT








Graphic Presentation of Water Quality Result of C5e - SHKC (Eastern)








Graphic Presentation of Water Quality Result of C5w - SHKC (Western)








Graphic Presentation of Water Quality Result of WSD21 - Wan Chai





Graphic Presentation of Water Quality Result of C7 - Windsor House









Remarks:

*Due to the Amber rainstorm signal was hoisted on 20 May 13 at ebb tide, the water quality monitoring was cancelled.





Graphic Presentation of Water Quality Result of C8 - City Garden







Graphic Presentation of Enhanced Water Monitoring Results (DO) at C6 - Excelsior Hotel







Graphic Presentation of Enhanced Water Monitoring Results (DO) at C7 - Windsor House



**Graphic Presentation of Enhanced Water Monitoring Results (DO) at Ex-WPCWA SW
- South-western corners of ex-Public Cargo Works Area**



**Graphic Presentation of Enhanced Water Monitoring Results (DO) at Ex-WPCWA SE
- South-eastern corners of ex-Public Cargo Works Area**

