












Graphic Presentation of Water Quality Result of C4e - WCT and GEC (Eastern)














Graphic Presentation of Water Quality Result of C4w - WCT and GEC (Western)

















Graphic Presentation of Enhanced Water Monitoring Results (DO) at C6 - Excelsior Hotel







Graphic Presentation of Enhanced Water Monitoring Results (DO) at C7 - Windsor House






Graphic Presentation of Enhanced Water Monitoring Results (DO) at Ex-WPCWA SE - South-eastern corners of ex-Public Cargo Works Area




Daily SS Moniotring at C7 - Windsor House

- ◆ SS level (mg/L)
- - - Action Level
- Limit Level



24hr Turbidity at C7 (NTU)



24hr Turbidity at C7 (NTU)

