





Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with Contractor of HY/2009/19, pile cap breaking works was conducted on 23, 24 June 2015; and pile cap excavation works was conducted 25 June 2015. Noise mitigation measures including temporary noise barrier was implemented for the breaking works by the Contractor while breaking works and excavation works was noted on-going at the construction site located next to the monitoring station. In view of the above, the exceedances were considered to be non-Project related and contributed by nearby non-CWB construction site works. Nevertheless, the Contractor was reminded to strengthen the noise mitigation measures implemented for the pile cap demolition works to avoid potential cumulative impact to nearby sensitive receivers.



Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)





Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)

