





Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with contractor HY/2009 19, no noisy construction activities were conducted during monitoring. Exceedance was considered to be contributed by the non CWB construction activities at the construction site next to Hong Kong Electric Centre




Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)





Graphic Presentation of Real Time Noise Monitoring Result (RTN2a- Hong Kong Electric Centre)



After checking with contractor HY/2009/19. No construction activities were conducted during the recorded period. Exceedances were contributed by Chinese New year pyrotechnic display.

After checking with contractor HY/2009/19, no noisy construction activities were conducted during the recorded period and the exceedance was non-continuous. Exceedances were considered to be contributed by nearby IEC traffic

After checking with contractor HY/2009/19. No construction activities were conducted during the recorded period. Exceedances were contributed by nearby IEC traffic