



Ref no.	Date	Location	Parameter (Unit)	Construction Noise Level, dB(A)	Action Level	Limit Level	Follow-up action
RTN_2020.04_1	8, 18, 20 and 21 April 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractor, concreting work was carried out for the parapet from P18 to P19 (edge fast lane nearer to seaside) on 8 April 2020, which was far from the station and blocked by the roadside barrier, and there was no construction works conducted under the Contractor HY/2009/19 around the monitoring station on 18, 20 and 21 April 2020 during the monitoring period. Meanwhile, renovation works was conducted at non-CWB construction site around the monitoring station and observed as major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.