



Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action
X_20N003	11-May-20	14:12	M4b - Victoria Centre	77	Leq(30min)	when one documented complaint was received.	75	Possible reason: Non-CWB project material handling work immediately next to the monitoring station and traffic nearby were observed as the major noise contribution during monitoring. Action taken / to be taken: A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. Remarks / Other Obs: No construction works was conducted under HY/2009/19 around the monitoring location while non-CWB project material handling work immediately next to the monitoring station was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_20N004	11-May-20	14:12	M4b - Victoria Centre	77	Leq(30min)	when one documented complaint was received.	75	Possible reason: Non-CWB project material handling work immediately next to the monitoring station and traffic nearby were observed as the major noise contribution during monitoring. Action taken / to be taken: A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. Remarks / Other Obs: No construction works was conducted under HY/2011/08 around the monitoring location while non-CWB project material handling work immediately next to the monitoring station was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref no.	Date	Location	Parameter (Unit)	Construction Noise Level, dB(A)	Action Level	Limit Level	Follow-up action
RTN_2020.04_1	27, 28, 29 April and 12, 13, 20 May 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractor, there was no construction works conducted under the Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 27, 28, 29 April and 12, 13, 20 May 2020 during the monitoring period. Meanwhile, renovation works was conducted at non-CWB construction site around the monitoring station and observed as major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.