



Ref. No.	Date	Location	Parameter	Construction Noise Level, dB(A)	Action Level	Limit Level dB(A)	Follow-up action
RTN_2020.09_1	28 Aug 2020 and 3 Sep 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 28 August and 3 September 2020. Meanwhile, renovation works was conducted at non-CWB construction site around the monitoring station and observed as major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
RTN_2020.09_2	2 and 3 Sep 2020	RTN 2a - Hong Kong Electric Centre	Leq (30min)		When one documented complaint was received.	75	
RTN_2020.09_3	2 and 3 Sep 2020	RTN 2a - Hong Kong Electric Centre	Leq (30min)		When one documented complaint was received.	75	
RTN_2020.09_4	15 and 16 Sep 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)		When one documented complaint was received.	75	After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 15 and 16 September 2020. As such, the exceedance was considered as non-Project related.
RTN_2020.09_5	15 and 16 Sep 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)		When one documented complaint was received.	75	

Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action
X_20N007	28-Sep-20	16:19	M4b - Victoria Centre	87	Leq(30min)	when one documented complaint was received.	75	<p>Possible reason: Non-CWB project construction work was conducted immediately next to the monitoring station and traffic nearby were observed as the major noise contribution during monitoring.</p> <p>Action taken / to be taken: A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure.</p> <p>Remarks / Other Obs: Concreting work to the road adjacent to Toyota maintenance shop at Watson Road was carried out under HY/2009/19 around the monitoring location. Temporary noise barrier was erected as noise mitigation measure for the works. Meanwhile, non-CWB project material handling work immediately next to the monitoring station was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.</p>
X_20N008	28-Sep-20	16:19	M4b - Victoria Centre	87	Leq(30min)	when one documented complaint was received.	75	<p>Possible reason: Non-CWB project construction work was conducted immediately next to the monitoring station and traffic nearby were observed as the major noise contribution during monitoring.</p> <p>Action taken / to be taken: A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure.</p> <p>Remarks / Other Obs: No construction works was conducted under HY/2011/08 around the monitoring location while non-CWB project material handling work immediately next to the monitoring station was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.</p>



Ref. No.	Date	Location	Parameter	Construction Noise Level, dB(A)	Action Level	Limit Level dB(A)	Follow-up action
RTN_2020.10_1	30 Sep, 5 and 6 Oct 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 30 September, 5 and 6 October 2020. As such, the exceedance was considered as non-Project related.
RTN_2020.10_2	30 Sep, 5 and 6 Oct 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)		When one documented complaint was received.	75	
RTN_2020.10_3	12, 21 and 23 Oct 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 12, 21 and 23 October 2020. As such, the exceedance was considered as non-Project related.
RTN_2020.10_4	12, 21 and 23 Oct 2020	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)		When one documented complaint was received.	75	



Ref. No.	Date	Location	Parameter	Construction Noise Level, dB(A)	Action Level	Limit Level dB(A)	Follow-up action
RTN_2020.11_1	6-Nov-20	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)	Refer to Appendix 5.4	When one documented complaint was received.	75	After checking with the Contractors, no construction activities was conducted under Contractor HY/2009/19 and HY/2011/08 around the monitoring station on 6 November 2020. As such, the exceedance was considered as non-Project related.
RTN_2020.11_2	6-Nov-20	RTN 1 - FEHD Hong Kong Transport Section Whitfield Depot	Leq (30min)		When one documented complaint was received.	75	