

Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N186	1-Dec-15	10:20	M1a-Habour Road Sports Centre	89	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Bored Pilling works and ground investigation works at portion 2 and reclamation works at WCR3 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N187	1-Dec-15	10:20	M1a-Habour Road Sports Centre	89	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						10001104.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of
								Remarks / Other Obs:	contractor's working procedure.  Welding works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N189	8-Dec-15	16:18	M1a-Habour Road Sports Centre	83	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N190	8-Dec-15	16:18	M1a-Habour Road Sports Centre	83	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						received.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement and mitigtaion measures including provision of noise screen and noise barrier was implemented. Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N192	11-Dec-15	10:05	M6 - HK Baptist Church Henrietta Secondary School	68	Leq(30-min)	when one documented complaint was received.	65	Possible reason:	Traffic nearby was observed during monitoring and was considered as the major noise contribution.
						·			Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	No construction work was conducted under Contract HY/2009/19 around the concerned location during the time of measurement and it was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N193	15-Dec-15	13:27	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N194	15-Dec-15	13:27	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						received.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement and mitigtation measures including provision of noise screen and noise barrier was implemented. Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N196	16-Dec-15	9:40	M6 - HK Baptist Church Henrietta Secondary School	69	Leq(30-min)	when one documented complaint was received.	65	Possible reason:	Traffic nearby was observed during monitoring and was considered as the major noise contribution.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	No construction work was conducted under Contract HY/2009/19 around the concerned location during the time of measurement and it was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.
X_10N197	23-Dec-15	13:42	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						received.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Contractor's working procedure.  Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_10N198	23-Dec-15	13:42	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						7000.04.		Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.  Excavation works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.