Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_16N001	12-Jan-16	11:00	M1a-Habour Road Sports Centre	79	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Backfilling and formation works at Portion 2 and bored pile and ground investigation at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N002	12-Jan-16	11:00	M1a-Habour Road Sports Centre	79	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						received.		Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Excavation works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N004	19-Jan-16	10:25	M1a-Habour Road Sports Centre	85	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking and piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Backfilling at Portion 2 and bored pile, diaphragm wall construction and ground investigation at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while pilling and breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N005	19-Jan-16	10:25	M1a-Habour Road Sports Centre	85	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking and piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Welding works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while piling and breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.