

X_16N007	16-Feb-16								
1		10:54	M1a-Habour Road Sports Centre	78	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII- CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Bored pile, diaphragm wall construction and ground investigation at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the
									monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N008	16-Feb-16	10:54	M1a-Habour Road Sports Centre	78	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						received.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Despite breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement, mitigtaion measures including the use of acoustic screen was provided. In addition, piling works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-
								D	Project related.
X_16N0010	23-Feb-16	10:34	M1a-Habour Road Sports Centre	82	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Bored pile, diaphragm wall construction and ground investigation at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N011	23-Feb-16	10:34	M1a-Habour Road Sports Centre	82	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
						receiveu.		Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Despite breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement, mitigtaion measures including the use of acoustic screen was provided. In addition, operation of multiple air compressors at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.