

Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_16N0013	2-Mar-16	15:53	M1a-Habour Road Sports Centre	80	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Diaphragm wall construction at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N014	2-Mar-16	15:53	M1a-Habour Road Sports Centre	80	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Despite breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement, mitigtaion measures including the use of acoustic covering was provided. In addition, operation of multiple air compressors at EX-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N0016	8-Mar-16	10:15	M1a-Habour Road Sports Centre	82	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Diaphragm wall construction at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N017	8-Mar-16	10:15	M1a-Habour Road Sports Centre	82	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure.
								Remarks / Other Obs:	Despite breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement, mitigtaion measures including the use of acoustic covering was provided. In addition, operation of multiple air compressors at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.
X_16N0019	15-Mar-16	10:15	M1a-Habour Road Sports Centre	81	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Diaphragm wall construction at Portion 5 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_16N020	15-Mar-16	10:15	M1a-Habour Road Sports Centre	81	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Operation of multiple air compressors at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Despite breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement, mitigtaion measures including the use of acoustic covering was provided. In addition, operation of multiple air compressors at EX-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre immediately opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.