Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N084	10-Jan-12		M1a - Harbour Road Sports Centre	71	Leq(5-min)	when one documented complaint was received.			Noisy traffic noise from Tonnochy Road and noise from training activities at swimming pool were contributed in the noise monitoring.
								Remarks / Other Obs:	Reviewed the trend of noise measurement results and analysis of contractor's working procedure. Review the basiline noise level at this monitoring station. No construction work for Contract no. HK/2009/02 was conducted during the measurement; It is concluded that the exceedance was not due to the Project.