

Contract No. HK/2015/01 Wanchai Development Phase II and Central Wanchai Bypass Sampling, Field Measurement and Testing Work (Stage3) Summary for Notification of Exceedance

Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_19C005	10-Jul-19	Mid-flood	RW21-P789	DO (mg/L)	5.32	3.02	2.44	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity (NTU)	31.29	11.35	12.71		Immediate repeated in-situ measurement to confirm the exceedances. Checked with Contractor works and reviewed previous monitoring data.
				SS (mg/L)	<2.0	18.42	27.54		No marine construction activity was conducted under Contract HK/2009/02 on the monitoring date. In view of the above, it is considered that the exceedance was not related to Project works. No exceedance
									was recorded in the subsequent monitoring on 10 July 2019 ebb tide.